

WELL NAME: APACHE CANYON 10-16V, API #: 071-07560, INSP. # 716301890




PHOTO 1: WELL SIGN



Network: Dec 18, 2025 at 10:08:32 AM MST
Local: Dec 18, 2025 at 10:08:32 AM MST
+37.093201, -104.978688
Los Animas County

PHOTO 2: LOCATION.



PHOTO 3: WELLHEAD AND EQUIPMENT.



**PHOTO 4: UNUSED OR UNUSEFUL EQUIPMENT (3" RISER OPEN TO ATMOSPHERE ON NORTH SIDE OF LOCATION). REMOVE
UNUSED OR UNUSEFUL EQUIPMENT PER RULE 606. CA DATE 1-18-2025.**



PHOTO 5: AREA OF IMPACTED SOIL NEAR COMPRESSOR. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,,(2).D. CA DATE 1-18-2025.



PHOTO 6: OIL IN PRIME MOVER ENGINE SKID WITHOUT WILDLIFE PROTECTION NET OR SCREEN (IT APPEARS THE ENGINE OIL HAS BEEN DRAINED DIRECTLY INTO ENGINE SKID AND LEFT, THIS PRACTICE SHOULD STOP IMMEDIATELY). DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 12-19-2025.



Network: Dec 18, 2025 at 10:10:44 AM
Local: Dec 18, 2025 at 10:10:44 AM
+37.093252, -104.9
Las Animas CO
Altitude: 2620.0
Speed: 2

PHOTO 7: OILY WASTE IN COMPRESSOR SKID WITHOUT WILDLIKE PROTECTION NET OR SCREEN. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 12-19-2025.