

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/18/2025

Submitted Date:

12/18/2025

Document Number:

719001036

FIELD INSPECTION FORM

Loc ID 306930 Inspector Name: GARCIA, CHARLES On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279557	WELL	PR	08/24/2005	CBM	067-09066	FEDERAL 01-02 2	PR

General Comment:

[Inspection Report Summary](#)
On 12/18/25 I Inspector Charles Garcia conducted an on-site inspection.
Location:FEDERAL 01-02 2
Operator:Simcoe LLC
API#: 067-09066
County: LaPlata

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	LOCATION SIGN AT ENTERANCE		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Contact # 970-247-6916 Emergency #911		Date:
Corrective Action:			
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	METER HOUSE TELEMETRY EQUIPMENT CATTLE PANELS		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
Type	OTHER		
Comment:	COMPRESSOR CATTLE PANELS SOUND WALL		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead # 1			corrective date
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment # 1			
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:			Date:
Type: Vertical Heated Separator # 1			
Comment:			
Corrective Action:			Date:

Type: Other	# 1		
Comment:	WELLHEAD		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	METER HOUSE CALIBRATION IN COMPLIANCE		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Check Dams	Pass					
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719001037	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7383182