

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/12/2025

Submitted Date:

12/12/2025

Document Number:

715801732

FIELD INSPECTION FORM

Loc ID 333225 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 16 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------------|-------|----------------------------------|---------------------------------|
| Santistevan, Brittani | | brittani.santistevan@state.co.us | |
| | | cogcc@kpk.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 239679 | WELL | SI | 05/01/2021 | OW | 123-07467 | CAMENISCH 1 | SI |

General Comment:

[This is a field audit of the scout card, related documents and the location. Follow up to FIR Doc# 715801374.](#)

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|--|-------|--|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Adequate, the sign is faded, & getting hard to read & needs to be updated. | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | Adequate, the sign is faded, & getting hard to read & needs to be updated. | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Adequate. | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | WEEDS | | |
| Comment: | Tall vegetation throughout the location & around the equipment needs to be removed. | | |
| Corrective Action: | comply with Rule 606 | Date: | 08/25/2025 |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|--|-------|--|
| Type | TANK BATTERY | | |
| Comment: | wood/metal post & barbwire needs attention | | |
| Corrective Action: | | Date: | |
| Type | PUMP JACK | | |
| Comment: | Fabricated round stock | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | wood/metal post & barbwire needs attention | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|-----------------------|-----|-------|-----------------|
| Type: Bird Protectors | # 2 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------------|---------------------------------------|--|-------|
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Vertical Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Prime Mover | # 1 | | |
| Comment: | electric motor | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 3 | | |
| Comment: | automation,electric panel & meter box | | |
| Corrective Action: | | | Date: |
| Type: Emission Control Device | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 1 | 300 BBLs | STEEL AST | | 40.073000,-104.866600 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--------------------------------------|---------------------|---------------------|-------------|
| Earth | | | | |
| Comment: | Vegetation needs to be cut & removed | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER | 1 | OTHER | FIBERGLASS AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

| | | | | |
|---|------------------------------------|---------------------|---------------------|-------------|
| Paint | | | | |
| Condition | | | | |
| Other (Content) | | | | |
| Other (Capacity) | 210 bbl | | | |
| Other (Type) | | | | |
| Berms | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | | | | |
| Comment: | Shares containment with crude tank | | | |
| Corrective Action: | | | | Date: |
| Wells Served By Facilities Above | | | | |
| API Number | | AirsID | | |
| 123-07467 | | API Number | AirsID | |
| Venting: | | | | |
| Yes/No | NO | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Flaring: | | | | |
| Type | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Inspected Facilities

Facility ID: 239679 Type: WELL API Number: 123-07467 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI, the well is part of a 901 Order.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 08/27/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Plumbed to surface

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>ECMC Inspection Report Summary On Friday 12-12-2025 at approximately 1315 hrs. I, Inspector Robbie Revas, Conducted an audit of the well scout card & related forms followed by an onsite inspection: Follow up to FIR # 715801374. Operator: KP Kauffman Location # 333225 API # 05-123-07467 Well name: Camenisch 1 County: Weld Weather: Cloudy Temp: 51* Location: Dry While there, I observed a wellsite & tank battery, SI at the time of inspection. During this inspection the following possible compliance issues were observed to have not been addressed since the previous FIR: 606 housekeeping: Tall vegetation needs to be removed, CA date 8-25-2025. Any corrective actions from previous inspections that have not been addressed are still applicable. See attached photos. Due to Non-Compliance with ECMC rules, this audit/inspection will be referred to ECMC Enforcement.</p> | revasr | 12/12/2025 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 404471787 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7373384 |
| 715801733 | Location photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7373377 |