

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/12/2025

Submitted Date:

12/12/2025

Document Number:

715801737

FIELD INSPECTION FORM

Loc ID 317651 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------------|-------|----------------------------------|---------------------------------|
| Santistevan, Brittani | | brittani.santistevan@state.co.us | |
| | | cogcc@kpk.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 239692 | WELL | SI | 05/01/2021 | GW | 123-07480 | SUCKLA-BROWN UNIT 1 | SI |

General Comment:

[This is a field audit of the scout card, related documents and the location.](#)

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | hidden by tall vegetation. | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|----------------------|-------|--|
| Comment: | <input type="text"/> | Date: | |
| Corrective Action: | <input type="text"/> | | |

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | WEEDS | | |
| Comment: | Tall vegetation along access road, throughout location & around all equipment needs to be removed. | | |
| Corrective Action: | Comply with Rule 606 | Date: | 08/25/2025 |

Overall Good:

Spills:

| Type | Area | Volume | |
|------|------|--------|--|
| | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|---|-------|--|
| Type | WELLHEAD | | |
| Comment: | fabricated steel pipe on the north side. | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | fabricated steel pipe around the ancillary equipment. | | |
| Corrective Action: | | Date: | |
| Type | PUMP JACK | | |
| Comment: | fabricated steel pipe around the pump jack | | |
| Corrective Action: | | Date: | |

Equipment:

| Type | | # | | corrective date |
|--------------------|----------------|-----|-------|-----------------|
| Prime Mover | | # 1 | | |
| Comment: | electric motor | | | |
| Corrective Action: | | | Date: | |
| Bradenhead | | # 1 | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Pump Jack | | # 1 | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |

| | | |
|---------------------------|--|-------|
| Type: Ancillary equipment | # 1 | |
| Comment: | electric panel, meter box & transformers | |
| Corrective Action: | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 239692 Type: WELL API Number: 123-07480 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI, the well is part of a 901 Order.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 06/30/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>ECMC Inspection Report Summary On Friday 12-12-2025 at approximately 1400 hrs. I, Inspector Robbie Revas, Conducted an audit of the well scout card & related forms followed by an onsite inspection: Operator: KP Kauffman Location # 317651 API # 05-123-07480 Well name: Suckla-Brown Unit 1 County: Weld Weather: Clear Temp: 51* Location: Dry While there, I observed a wellsite, SI at the time of inspection. During this inspection the following possible compliance issues were observed & have not been addressed since the previous inspection: 606 housekeeping: Tall vegetation needs to be removed, CA date 8-25-2025. Any corrective actions from previous inspections that have not been addressed are still applicable. See attached photos. Due to Non-Compliance with ECMC rules, this audit/inspection will be referred to ECMC Enforcement.</p> | revasr | 12/12/2025 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 404471791 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7373386 |
| 715801738 | location photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7373375 |