

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/19/2025

Submitted Date:

12/19/2025

Document Number:

708908073

FIELD INSPECTION FORM

Loc ID 311552 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
TEP		ECMCInspectionReports@flywheelenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210761	WELL	PR	02/26/1987	GW	045-06519	HOAGLUND W-32-35	PR

General Comment:

[This is a Desktop Inspection/Audit of the scout card & related documents.](#)

Inspected Facilities

Facility ID: 210761 Type: WELL API Number: 045-06519 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary On 12/19/2025 at approximately 15:15 hours, I, Compliance Specialist, Wayne Smelser Conducted a desktop follow up inspection/audit of TEP ROCKY MOUNTAIN LLC HOAGLUND W-32-35 Location # 311552 in Garfield County Colorado. Please refer to desktop inspection/audit 708907870 conducted on 11/13/2025, previous corrective action has been completed. Wellbore diagram submitted by operator on 11/19/2025 Location is within High Priority/Density/Black Bear Habitat areas/Bald Eagle Roost site & in close proximity to NSO Habitat area. Location is within Rule 411a Surface Water External Buffer. Location is approximately 105 yards from the Colorado River.</p> <p>This is a summary of desktop follow up inspection/audit report.</p>	<p>smelserw</p>	<p>12/19/2025</p>