

Interim Reclamation and Stormwater Inspection

December 16, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 331223

Location Name: HSR-PARKER #15-16A

Inspection Document #: 718601254

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HSR-PARKER #15-16A
Location ID: 331223



Photo 1. Looking north down the access road. It appears that a portion of the access road has been disturbed by construction unrelated to oil and gas. See photo 10.



Photo 2. Picture taken at the bend in the access road. It appears that a power box and meter unrelated to oil and gas were recently installed near the location.



Inspection Photos
Location Name: HSR-PARKER #15-16A
Location ID: 331223



Photo 3. Looking northeast down the access road. It appears that desirable vegetation has established on the former access road. The access road appears to be reflective of the surrounding area.



Photo 4. Looking north across the north side of the location. Non oil and gas electric box is visible.

Inspection Photos
Location Name: HSR-PARKER #15-16A
Location ID: 331223



Photo 5. Looking west across the well location. No oil and gas equipment remains on location. Desirable perennial vegetation is present on the location and appears to have reached 80% coverage of the reference area.



Photo 6. Looking south from the wellbore area. See photo 5 comments.



Inspection Photos
Location Name: HSR-PARKER #15-16A
Location ID: 331223



Photo 7. Looking east from the wellbore area. See photo 5 comments.



Photo 8. Looking north from the wellbore area. See photo 5 comments.



Inspection Photos
Location Name: HSR-PARKER #15-16A
Location ID: 331223



Photo 9. Reference vegetation to the west of the location.



Photo 10. Google earth aerial imagery taken 11/2025. Construction that appears unrelated to oil and gas has disturbed a portion of the former access road and location.