

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/16/2025

Submitted Date:

12/22/2025

Document Number:

720900478

FIELD INSPECTION FORM

Loc ID 304675 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

Findings:

16 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|--------------|------------------------------|---------|
| Dolezal, Pat | 970-332-3585 | pat.dolezal@ownresources.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 272005 | WELL | PR | 06/15/2004 | GW | 125-08850 | DEVLIN 31-9 | PR |

General Comment:

[This is a field audit of the scout card, related documents and the location.](#)

| Location | | | |
|--|---|--------|-----------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Two track off maintained County Road. | | |
| Corrective Action: | | Date: | |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | OTHER | | |
| Comment: | Lease sign posted at access trail intersection. | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Lease sign at wellhead location. | | |
| Corrective Action: | | Date: | |
| Emergency Contact Number: | | | |
| Comment: | Emergency contact information posted on Lease sign. | | Date: _____ |
| Corrective Action: | | | |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Stock panel fencing around surface equipment at well location. | | |
| Corrective Action: | | Date: | |
| Equipment: | | | |
| Type: Ancillary equipment | # 1 | | corrective date |
| Comment: | Wellhead. Casing production. Rods and tubing in the wellbore. Tubing valve open. Casing valve open. | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | Electric Motor. | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Bradenhead plumbed to surface. | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Digital Gas Meter Run. Meter Calibration/Test Log dated . Well Inlet Valve open. Gas Outlet Valve open. | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--|-------|--|
| Type: Other | # 1 | | |
| Comment: | Flowline mounted Meter Run Box. | | |
| Corrective Action: | | Date: | |
| Type: Dehydrator | # 1 | | |
| Comment: | Dehydrator (Drip Bottle) on gas meter run inlet. | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Pump Jack Power and Control Panel. | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Vertical Separator | # 0 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Location Construction

Location ID: 272005 CDP: _____

Comment:

Corrective Action:

Date: _____

Form 2A COAs:

Comment: No COA's.

Corrective Action:

Date: _____

Wildlife BMPs:

Comment:

Corrective Action:

Date: _____

Comment:

Corrective Action:

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: 272005 Type: WELL API Number: 125-08850 Status: PR Insp. Status: PR

Producing Well

Comment: Rods and tubing in wellbore. Tubing valve open. Casing valve open. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open.
Electronic Well File reflects last Production/Status reported 10/1/2025 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 720900493 | Field audit photos. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7387022 |