

Inspection Photos

December 12th, 2025

Operator: Nuevida Resources

Location ID: 484496

Inspection Document #: 714003037

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ardourel
Location ID: 484496

December 12, 2025
138° SE



Photo 1. Ground view of the southern TUA pad taken from the western edge facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

December 12, 2025
0° N



Photo 2. Unused fabric/mats piled on the western edge of the TUA pad.

December 12, 2025
235° SW



Photo 3. Gully erosion (and sediment deposition) persisting in the SW corner of the TUA cut slope area.



Inspection Photos
Location Name: Ardourel
Location ID: 484496

December 12, 2025
65° NE



Photo 4. Pooling water observed on the southern edge of the TUA pad.

December 12, 2025
289° W



Photo 5. Pooling water occurring in the NE corner and along the northern edge of the TUA pad.

December 12, 2025
281° W



Photo 6. View of topsoil pile covered in annual weeds included but not limited to Kochia, Red Stem Filaree and Cheatgrass. Note: Top soil pile is representative of all other topsoil piles on both the well pad and TUA pad.



Photo 6. Holes/punctures observed on TUA perimeter berm liner. Existing patch jobs were not successful and holes persist.

Inspection Photos
Location Name: Ardourel
Location ID: 484496



Photo 8. Various unused tubing observed around the location.

December 12, 2025
158° S



Photo 9. Unused piping stored on the western edge of the well pad.

December 12, 2025
104° E



Photo 10. Pooling water observed on the well pad.

December 12, 2025
166° S



Photo 11. Vehicle tracking observed on the western edge of the well pad. Tracking is consistent with tracking observed throughout the well pad.

Inspection Photos
Location Name: Ardourel
Location ID: 484496

December 12, 2025
91° E



Photo 12. Tanks in the northeast corner of the well pad remain unmarked. Physical markings on each individual tank is required.



Photo 13. Wildlife protections/coverings at the both the well pads and chem/lube tank secondary containment are insufficient/no longer functioning and need maintenance/replacing.