

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/16/2025

Submitted Date:

12/22/2025

Document Number:

719500748

FIELD INSPECTION FORM

Loc ID 323895 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 51130
Name of Operator: LOCIN OIL CORPORATION
Address: 23501 CINCO RANCH BLVD, B244
City: KATY State: TX Zip: 77494

Findings:

14 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
DePaolo, Corey		corey.depaolo@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
119484	PIT	AC	02/11/2020		-	Government #14-2 119484	AC
211115	WELL	SI	06/01/2020	GW	045-06874	GOVT. 14-2 (OWP)	SI

General Comment:

This is a field audit of the location, scout card, and related documents.

On 12/17/2025 at approximately 14:05, Compliance Inspector Matthew Morris conducted a follow-up audit at LOCIN OIL CORPORATION, GOVT.-68S104W/2SWSW (OWP) at Location ID #323895 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	No labels on chemical tank near wellhead. Fluid in tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	_____

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds in pit.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Stained soil near separator.		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Livestock fencing		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Livestock fencing		
Corrective Action:		Date:	
Type	TANK BATTERY		

Comment: Livestock fencing		
Corrective Action:		Date:

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment: Wildlife entry hazards on gas meter housing.			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment: Chemical tank			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLs	STEEL AST		,
Comment: Open-ended line on check valve on top of AST.					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	210 bbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	PLASTIC AST		,
Comment: Missing cover on AST poses a wildlife entry hazard.					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	

Other (Capacity) 37 bbls	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 119484 Type: PIT API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 211115 Type: WELL API Number: 045-06874 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Compaction						
Gravel						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: _____ Lined: NO Pit ID: 119484 Lat: 39.392741 Long: -108.962383

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: Weeds present in pit.

Corrective Action Date: _____

Fencing:

Fencing Type: Livestock Fencing Condition: _____

Comment:

Corrective Action Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action Date: _____

ECMC Comments

Comment	User	Date
During the audit, the following compliance issue(s) were observed: 1) Unlabeled chemical tank near wellhead (fluid in tank) 2) Stained soil near separator 3) Wildlife entry hazards at gas meter housing 4) Open-ended line on check valve on top of steel AST 5) Missing cover/wildlife entry hazard on plastic AST	morris	12/22/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719500749	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7388315