

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 21C-25 (MESA 10) Pad

Location #: 335105



Photo # 4811 From entrance to location



Photo # 4812 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 21C-25 (MESA 10) Pad

Location #: 335105



Photo # 4813 Location



Photo # 4814 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 21C-25 (MESA 10) Pad

Location #: 335105



Photo # 4815 Location




Photo # 4816 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 21C-25 (MESA 10) Pad

Location #: 335105



Photo # 4817 Location



Photo # 4818 Mechanical Condition - Possible separator leak & staining near separator

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 21C-25 (MESA 10) Pad

Location #: 335105



Photo # 4819 Mechanical Condition - Possible separator leak & staining near separator



Photo # 4820 Mechanical Condition - Possible separator leak & staining near separator

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 21C-25 (MESA 10) Pad

Location #: 335105



Photo # 4821 Mechanical Condition - Possible separator leak & staining near separator



Photo # 4822 Mechanical Condition - Possible separator leak & staining near separator

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 21C-25 (MESA 10) Pad

Location #: 335105



Photo # 4823 Mechanical Condition - Possible separator leak & staining near separator

Photo # 4824 Mechanical Condition - Possible separator leak & staining near separator