

FORM
INSPRev
X/20

State of Colorado Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/19/2025

Submitted Date:

12/23/2025

Document Number:

719200585

FIELD INSPECTION FORM

Loc ID 323875 Inspector Name: Gaasche, Emily On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 3 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		ECMCInspectionReports@flywheelenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211063	WELL	PA	11/06/2013	GW	045-06821	MILLER 1	RI
323875	LOCATION	CL			-	MILLER-66S91W 31SESE	RI

General Comment:

On 12/19/2025, NW Reclamation Specialist Emily Gaasche conducted a final reclamation inspection at TEP Rocky Mountain LLC's Miller #1 location in Garfield County, Colorado.

The location is within High Priority Habitats - Elk Severe Winter Range, Mule Deer Severe Winter Range, Mule Deer Winter Concentration Area and is in close proximity to Aquatic Native Species Conservation Waters.

This inspection is a follow-up to #718100115 and #719200033 to document compliance with the following corrective actions:
-Final Reclamation
-Weed Management

It was observed in this inspection that the corrective actions remain outstanding.

Refer to the Reclamation section of this report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Corrective action(s) from the previous inspection that have not been addressed are still applicable.

Inspected Facilities

Facility ID: 211063 Type: WELL API Number: 045-06821 Status: PA Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 323875 Type: LOCATION API Number: - Status: CL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action: _____ Date _____

CA per inspection #719200033, 718100115 and #696206124: Conduct reclamation in accordance with ECMC 1004 rules at the Location and access road. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local soil conservation district. Comply with Rule 1002.f and implement control measures to stabilize the seeded soil. Comply with 1004.e and 606.c.: Oil and Gas Locations will be kept free of all Undesirable Plant Species. Ongoing weed and stormwater monitoring/management required until Location receives a passing final reclamation inspection.

Overall Final Reclamation **Fail** Well Release on Active Location Multi-Well Location

ECMC Comments

Comment	User	Date
<p>Reclamation Comments:</p> <p>Inspection #718100115 and #696206124 observed that final reclamation has not been performed pursuant to 1004 Rules: O&G Access road to Location has not been reclaimed and the Location is not progressing towards 1004 reclamation standards; perennial establishment is not uniform and Location is predominantly bare, or vegetated by Undesirable Plant Species; including noxious weeds such as Jointed Goatgrass and Knapweed. Reclamation of the access road, as well as additional reclamation and weed management efforts at the Location required. Inspection required Operator to comply with ECMC 1004 Rules (including 1004.e and 606.c), and 1002.f by 11/15/2024.</p> <p>Inspection #719200033 performed a follow-up reclamation inspection during the growing season. Yellow salsify, bindweed and jointed goatgrass was dominant throughout the location. It did not appear as though additional reclamation work has been performed, including weed management efforts and BMPs to stabilize the seeded soils implemented; access road has not been recontoured/regraded and reclaimed.</p> <p>This inspection was performed during the dormant season. No additional reclamation efforts were evident. An undesirable weedy species, likely prickly Russian thistle or kochia, has overtaken the PA'd well marker area. Russian knapweed skeletons were observed at the location. It does not appear as though weed management efforts have been conducted in 2025. The access road remains and regrading/recontouring is not apparent. Additionally, no Resolution stating corrective actions have been performed or completed has been submitted by the Operator pursuant to Rule 210.b.</p> <p>This CA remains applicable.</p>	gaaschee	12/23/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719200586	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7389447