

Inspection Photos
Location Name: Clark, Francis Doughty 2
Location ID: 318444



Photo 1 Spill Location.



Photo 2 Backhoe & Excavation.

Inspection Photos
Location Name: Clark, Francis Doughty 2
Location ID: 318444



Photo 3 Contaminated soil pile.

Photo 4 Marked flow line.

Inspection Photos
Location Name: Clark, Francis Doughty 2
Location ID: 318444




Photo 5 Old KP Kauffman battery sign marking the flow line area.

Photo 6 Contaminated soil pile.

Inspection Photos
Location Name: Clark, Francis Doughty 2
Location ID: 318444



Photo 7 Excavation hole exposing flow lines.



Photo 8 Excavation hole exposing flow lines.

Inspection Photos
Location Name: Clark, Francis Doughty 2
Location ID: 318444



Photo 9 Excavation hole exposing flow lines.

Photo 10 Excavation hole exposing flow lines.

Inspection Photos
Location Name: Clark, Francis Doughty 2
Location ID: 318444



Photo 11 Wellsite.

Photo 12 Wellhead.

Inspection Photos
Location Name: Clark, Francis Doughty 2
Location ID: 318444



Photo 13 Wellsite sign.

Photo 14 Wellsite with the spill excavation work in the background.

Inspection Photos
Location Name: Clark, Francis Doughty 2
Location ID: 318444



Photo 15 Wellsite ancillary equipment.

Photo 16 Wellsite.