

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/16/2025

Submitted Date:

12/23/2025

Document Number:

719500754

**FIELD INSPECTION FORM**

Loc ID 312371 Inspector Name: Morris, Matthew On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 51130  
Name of Operator: LOCIN OIL CORPORATION  
Address: 23501 CINCO RANCH BLVD, B244  
City: KATY State: TX Zip: 77494

**Findings:**

- 13 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Heil, John		john.heil@state.co.us	
GAS, UTAH		inspections@utahgascorp.com	
DePaolo, Corey		corey.depaolo@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
112125	PIT		09/23/1999		-	CULVER 1	
221344	WELL	SI	05/01/2025	GW	077-05137	CULVER-GOV'T 1 (OWP)	SI

**General Comment:**

This is a field audit of the location, scout card, and related documents.

On 12/16/2025 at approximately 13:20, Compliance Inspector Matthew Morris conducted an on-site audit at LOCIN OIL CORPORATION, CULVER-GOV'T-68S104W/28SESE (OWP) at Location ID #312371 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Two (2) plastic ASTs are unlabeled.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds present in pit and near wellhead.		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Pipe rails		
Corrective Action:		Date:	
Type	PIT		
Comment:	Livestock fencing		
Corrective Action:		Date:	

**Equipment:**

Type: Horizontal Separator	# 1		corrective date
Comment:	Gas leak on pressure monitoring tubing on separator.		

Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter shows production. Gas meter calibrated by Utah Gas Corp in December of 2025. Operator (Locin) is in OWP.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	2	OTHER	PLASTIC AST		,
Comment:	1) Leak seeping from PVC plug near bottom of tank 2) Open-ended lines on top neck of ASTs				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	Not posted
Other (Capacity)	Not posted
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 112125 Type: PIT API Number: - Status: \_\_\_\_\_ Insp. Status: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 221344 Type: WELL API Number: 077-05137 Status: SI Insp. Status: SI

**Producing Well**

Comment: Well status is SI. Well appears to be producing. Operator is in OWP.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
Berms						
Gravel						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: \_\_\_\_\_ Lined: NO Pit ID: 112125 Lat: 39.333945 Long: -108.986641

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: Weeds present in pit.

Corrective Action

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Livestock Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: Mesh Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**ECMC Comments**

Comment	User	Date
<p>During the audit, the following compliance issue(s) were observed:</p> <ul style="list-style-type: none"> <li>1) Two (2) plastic ASTs are unlabeled</li> <li>2) Weeds present in pit and at wellhead</li> <li>3) Gas meter shows production and has been calibrated by UGC; Operator (Locin) is in OWP</li> <li>4) Gas leak on pressure monitoring tubing at separator</li> <li>5) Leak seeping from PVC plug on bottom of plastic AST</li> <li>6) Open-ended lines on top necks of ASTs</li> <li>7) Well status shows SI; well appears to be producing. Operator is in OWP</li> </ul>	morrism	12/23/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719500755	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7389881">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7389881</a>
719500756	Separator Gas Leak	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7389882">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7389882</a>