

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/16/2025

Submitted Date:

12/23/2025

Document Number:

717100444

**FIELD INSPECTION FORM**

Loc ID: 329498 Inspector Name: Rollins, Grace On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Chevron Inspections</a>
Graber, Nikki		nikki.graber@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249632	WELL	PA	05/10/2024	GW	123-17435	KY BLUE H 25-15	EI
489958	SPILL OR RELEASE	AC	04/28/2025		-	KY Blue H 25-10 Flowline	EI
489959	SPILL OR RELEASE	AC			-	KY Blue H 25-15 Flowline	EI
490198	SPILL OR RELEASE	AC			-	KY Blue H 25-15 Flowline	EI

**General Comment:**

ECMC Field Inspection Report Summary

This is an environmental inspection to determine progress on Spill IDs 489958, 489959, & 490198 and Remediation Project # 32903. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Site/Spill Name: KY Blue H 25-15 Flowline

Spill IDs: 489958, 489959, & 490198

Remediation Project #: 32903

Well API #: 05-123-17435

Reported Dates of Discovery: 4/23/2025 (489958 & 489959) and 5/14/2025 (490198)

Spills have been Open: 244 days & 223 days

Date of Inspection: 12/16/2025

Weather: Partly cloudy, 66°F

Current site status:

-The excavations at the spill locations have been backfilled.

See attached corrective actions. Forms 19 and 27 are required.

**Inspected Facilities**

Facility ID: 249632 Type: WELL API Number: 123-17435 Status: PA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 489958 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 489959 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 490198 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Spill IDs 489958, 489959, & 490198 were created to address the remediation of impacts identified at the KY Blue H 25-15 Flowline and remain unresolved. The excavations at the spill locations have been backfilled.

Corrective Action: Pursuant to Rule 912.b.(6) Operator was required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure. The Form 19 — Supplemental Report for closure was due by 07/22/2025 (489958 & 489959) and 08/12/2025 (490198). Operator shall submit delinquent form(s) for this project. Date: 08/12/2025

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Spill/Remediation:**

Comment: Remediation Project # 32903 was created for the plugging and abandonment of the KY Blue H 25-15 well and decommissioning of the associated flowline. Quarterly reporting is required under Remediation Project # 32903. The last Form 27 for this project was submitted 06/13/2025 (Document # 404176685) and denied by ECMC on 07/07/2025; a replacement Form has not been received.

Corrective Action: In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule (90 days). Operator shall provide an updated Form 27 for Remediation Project # 32903. Date: 07/07/2025

Emission Control Burner (ECB): \_\_\_\_\_

Comment:

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717100445	ECMC Photo Log - KY Blue H 25-15 Flowline - 12.16.2025	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7389952">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7389952</a>