

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/17/2025

Submitted Date:

12/17/2025

Document Number:

708908064

**FIELD INSPECTION FORM**

Loc ID 335092 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10844  
Name of Operator: QB ENERGY OPERATING LLC  
Address: 1001 17TH STREET SUITE 1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
QB ENERGY		ecmc.inspections@qb-energy.com	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Katz, Aaron		aaron.katz@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276856	WELL	PR	06/27/2006	GW	045-10533	PUCKETT 14C-31D	PR
276857	WELL	PR	07/25/2006	GW	045-10534	PUCKETT 23C-31D	PR
276858	WELL	PR	07/01/2025	GW	045-10535	PUCKETT 13D-31D	PR
276859	WELL	SI	04/01/2025	GW	045-10536	PUCKETT 24C-31D	SI
276860	WELL	SI	09/01/2025	GW	045-10537	PUCKETT 23D-31D	SI

**General Comment:**

[This is a Desktop Inspection/Audit of the scout card & related documents.](#)

**Inspected Facilities**

Facility ID: 276856 Type: WELL API Number: 045-10533 Status: PR Insp. Status: PR

**Producing Well**

**Comment:** After review of well records and COGIS Online, the coordinates for this well appear to be incorrect/not in compliance with CECMC Rules 216 & 414 - Drilling Completion Report & Scout Card records "as drilled" coordinates appear to be off by approximately 15 ft

Additionally the "as drilled" coordinates for the PUCKETT 23C-31D, PUCKETT 13D-31D, PUCKETT 24C-31D & PUCKETT 23D-31D wells appear to be incorrect/not in compliance with CECMC Rules 216 & 414

Well lacks wellbore diagram/not in compliance with CECMC Rule 420 - Comply with CECMC Rule 420 & submit wellbore diagram via FORM 4 SUNDRY or FORM 17

**Corrective Action:** **Comply with CECMC Rules 216 & 414** **Date:** 01/16/2026

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 276857 Type: WELL API Number: 045-10534 Status: PR Insp. Status: PR

**Producing Well**

**Comment:** Well lacks wellbore diagram/not in compliance with CECMC Rule 420

Additionally the PUCKETT 14C-31D, PUCKETT 13D-31D, PUCKETT 24C-31D & PUCKETT 23D-31D wells also lack wellbore diagrams/not in compliance with CECMC Rule 420

After review of well records and COGIS Online, the coordinates for this well appear to be incorrect/not in compliance with CECMC Rules 216 & 414 - Drilling Completion Report & Scout Card records "as drilled" coordinates appear to be off by approximately 10 ft

**Corrective Action:** **Comply with CECMC Rule 420 & submit wellbore diagrams via FORM 4 SUNDRY or FORM 17** **Date:** 01/16/2026

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 276858 Type: WELL API Number: 045-10535 Status: PR Insp. Status: PR

**Producing Well**

**Comment:** Well lacks wellbore diagram/not in compliance with CECMC Rule 420 - Comply with CECMC Rule 420 & submit wellbore diagram via FORM 4 SUNDRY or FORM 17

After review of well records and COGIS Online, the coordinates for this well appear to be incorrect/not in compliance with CECMC Rules 216 & 414 - Drilling Completion Report & Scout Card records "as drilled" coordinates appear to be off by approximately 8 ft

**Corrective Action:** **Date:**

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 276859 Type: WELL API Number: 045-10536 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

**Comment:** Well lacks wellbore diagram/not in compliance with CECMC Rule 420 - Comply with CECMC Rule 420 & submit wellbore diagram via FORM 4 SUNDRY or FORM 17

After review of well records and COGIS Online, the coordinates for this well appear to be incorrect/not in compliance with CECMC Rules 216 & 414 - Drilling Completion Report & Scout Card records "as drilled" coordinates appear to be off by approximately 21 ft

**Corrective Action:** **Date:**

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 276860 Type: WELL API Number: 045-10537 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

**Comment:** Well lacks wellbore diagram/not in compliance with CECMC Rule 420 - Comply with CECMC Rule 420 & submit wellbore diagram via FORM 4 SUNDRY or FORM 17  
 After review of well records and COGIS Online, the coordinates for this well appear to be incorrect/not in compliance with CECMC Rules 216 & 414 - Drilling Completion Report & Scout Card records "as drilled" coordinates appear to be off by approximately 27 ft

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary                      On 12/17/2025 at approximately 10:45 hours, I, Compliance Specialist, Wayne Smelser Conducted a desktop inspection/audit of QB ENERGY OPERATING LLC PUCKETT-66S96W 31NESW                      Location # 335092 in Garfield County Colorado.                      Location is within High Priority/Density/Black Bear Habitat areas &amp; in close proximity to NSO Habitat area.                      Location is approximately 260 yards from Starkey Gulch.</p> <p>During this desktop inspection/audit the following compliance issues were observed:</p> <p>1. Inspected Facilities - PUCKETT 14C-31D, PUCKETT 23C-31D, PUCKETT 13D-31D, PUCKETT 24C-31D &amp; PUCKETT 23D-31D wells lack wellbore diagrams - Comply with Rule 420 with a CA date of 01/16/2026</p> <p>2. Inspected Facilities - "as drilled" coordinates for the PUCKETT 14C-31D, PUCKETT 23C-31D, PUCKETT 13D-31D, PUCKETT 24C-31D &amp; PUCKETT 23D-31D wells appear to be incorrect - Comply with CECMC Rules 216 &amp; 414 with a CA date of 01/16/2026</p> <p>A follow up on this desktop inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.                      This is a summary of desktop inspection/audit report.</p>	smelserw	12/17/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404477469	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7380011">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7380011</a>
708908065	Inspection/Audit 708908064 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7380010">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7380010</a>