

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/17/2025

Submitted Date:

12/17/2025

Document Number:

708908067

FIELD INSPECTION FORM

Loc ID 335393 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
QB ENERGY		ecmc.inspections@qb-energy.com	
Katz, Aaron		aaron.katz@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275498	WELL	PR	12/28/2005	GW	045-10328	PUCKETT 44A-30D	PR
275499	WELL	SI	08/01/2025	GW	045-10329	PUCKETT 34B-30D	SI
275500	WELL	SI	08/01/2025	GW	045-10330	PUCKETT 44B-30D	SI
275501	WELL	PR	12/28/2005	GW	045-10331	PUCKETT 34A-30D	PR
275517	WELL	PR	12/28/2005	GW	045-10337	PUCKETT 34D-30D	PR
275518	WELL	SI	04/01/2025	GW	045-10338	PUCKETT 44D-30D	SI

General Comment:

[This is a Desktop Inspection/Audit of the scout card & related documents.](#)

Inspected Facilities				
Facility ID: <u>275498</u>	Type: <u>WELL</u>	API Number: <u>045-10328</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
<p>Comment: Well lacks wellbore diagram/not in compliance with CECMC Rule 420</p> <p>Additionally the PUCKETT 34B-30D, PUCKETT 44B-30D, PUCKETT 34A-30D, PUCKETT 34D-30D & PUCKETT 44D-30D wells also lack wellbore diagrams/not in compliance with CECMC Rule 420</p>				
<p>Corrective Action: Comply with CECMC Rule 420 & submit wellbore diagrams via FORM 4 SUNDRY or FORM 17</p>			<p>Date: <u>01/16/2026</u></p>	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: <u>275499</u>	Type: <u>WELL</u>	API Number: <u>045-10329</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Idle Well				
Purpose: <input type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
<p>Comment: Well lacks wellbore diagram/not in compliance with CECMC Rule 420 - Comply with CECMC Rule 420 & submit wellbore diagram via FORM 4 SUNDRY or FORM 17</p> <p>After review of well records and COGIS Online, the coordinates for this well appear to be incorrect/not in compliance with CECMC Rules 216 & 414 - Drilling Completion Report & Scout Card records "as drilled" coordinates appear to be off by approximately 8-10 ft</p>				
<p>Corrective Action:</p>			<p>Date:</p>	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: <u>275500</u>	Type: <u>WELL</u>	API Number: <u>045-10330</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Idle Well				
Purpose: <input type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
<p>Comment: Well lacks wellbore diagram/not in compliance with CECMC Rule 420 - Comply with CECMC Rule 420 & submit wellbore diagram via FORM 4 SUNDRY or FORM 17</p> <p>After review of well records and COGIS Online, the coordinates for this well appear to be incorrect/not in compliance with CECMC Rules 216 & 414 - Drilling Completion Report & Scout Card records "as drilled" coordinates appear to be off by approximately 8-10 ft</p>				
<p>Corrective Action:</p>			<p>Date:</p>	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: <u>275501</u>	Type: <u>WELL</u>	API Number: <u>045-10331</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
<p>Comment: Well lacks wellbore diagram/not in compliance with CECMC Rule 420 - Comply with CECMC Rule 420 & submit wellbore diagram via FORM 4 SUNDRY or FORM 17</p> <p>After review of well records and COGIS Online, the coordinates for this well appear to be incorrect/not in compliance with CECMC Rules 216 & 414 - Drilling Completion Report & Scout Card records "as drilled" coordinates appear to be off by approximately 8-10 ft</p>				
<p>Corrective Action:</p>			<p>Date:</p>	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: <u>275517</u>	Type: <u>WELL</u>	API Number: <u>045-10337</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Producing Well

Comment: Well lacks wellbore diagram/not in compliance with CECMC Rule 420 - Comply with CECMC Rule 420 & submit wellbore diagram via FORM 4 SUNDRY or FORM 17

After review of well records and COGIS Online, the coordinates for this well appear to be incorrect/not in compliance with CECMC Rules 216 & 414 - Drilling Completion Report & Scout Card records "as drilled" coordinates appear to be off by approximately 8-10 ft

Corrective Action: _____ **Date:** _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 275518 Type: WELL API Number: 045-10338 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well lacks wellbore diagram/not in compliance with CECMC Rule 420 - Comply with CECMC Rule 420 & submit wellbore diagram via FORM 4 SUNDRY or FORM 17

After review of well records and COGIS Online, the coordinates for this well appear to be incorrect/not in compliance with CECMC Rules 216 & 414 - Drilling Completion Report & Scout Card records "as drilled" coordinates appear to be off by approximately 8-10 ft

Corrective Action: _____ **Date:** _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary</p> <p>On 12/17/2025 at approximately 18:15 hours, I, Compliance Specialist, Wayne Smelser Conducted a desktop inspection/audit of QB ENERGY OPERATING LLC PUCKETT-66S96W 31NWNE Location # 335393 in Garfield County Colorado. Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area. Location is approximately 425 yards from Starkey Gulch.</p> <p>During this desktop inspection/audit the following compliance issues were observed:</p> <p>1. Inspected Facilities - PUCKETT 44A-30D, PUCKETT 34B-30D, PUCKETT 44B-30D, PUCKETT 34A-30D, PUCKETT 34D-30D & PUCKETT 44D-30D wells lack wellbore diagrams - Comply with Rule 420 with a CA date of 01/16/2026</p> <p>Comments -</p> <p>"as drilled" coordinates for the PUCKETT 34B-30D, PUCKETT 44B-30D, PUCKETT 34A-30D, PUCKETT 34D-30D & PUCKETT 44D-30D wells appear to be incorrect/not in compliance with CECMC Rules 216 & 414 - Drilling Completion Report & Scout Card records "as drilled" coordinates appear to be off by approximately 8-10 ft on each well.</p> <p>A follow up on this desktop inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This is a summary of desktop inspection/audit report.</p>	smelserw	12/17/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404478617	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7381260