

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/18/2025

Submitted Date:

12/18/2025

Document Number:

716301890

FIELD INSPECTION FORM

Loc ID 308128 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Findings:

- 13 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
BACA, DAVE	719-859-4066	dbaca@ogrisop.com	All Inspections
B WARD, GIENA		gward@ogrisop.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262543	WELL	PR	04/01/2024	CBM	071-07560	APACHE CANYON 10-16V	PR
291908	PIT	AC	08/28/2008		-	APACHE CANYON 10-16V	AC
426648	TANK BATTERY	AC	04/14/2009		-	APACHE CANYON-634S68W 10SESE	AC

General Comment:

"This is a field audit of the scout card, related documents and the location."

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type			
Comment:	SIGN HAS NO API# POSTED.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	PHOTO 5: AREA OF IMPACTED SOIL NEAR COMPRESSOR.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D.		Date: <u>01/18/2026</u>
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 4: UNUSED OR UNUSEFUL EQUIPMENT (3" RISER OPEN TO ATMOSPHERE ON NORTH SIDE OF LOCATION).		
Corrective Action:	REMOVE UNUSED OR UNUSEFUL EQUIPMENT PER RULE 606.		Date: <u>01/18/2026</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
			corrective date
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment: FORM 4 IS ATTACHED			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment: IS ACCESSABLE			

Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 262543 Type: WELL API Number: 071-07560 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 12/10/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291908 Type: PIT API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 426648 Type: TANK API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Culverts	Pass			

Comment: PHOTO 6: OIL IN PRIME MOVER ENGINE SKID WITHOUT WILDLIKE PROTECTION NET OR SCREEN (IT APPEARS THE ENGINE OIL HAS BEEN DRAINED DIRECTLY INTO ENGINE SKID AND LEFT, THIS PRACTICE SHOULD STOP IMMEDIATELY). PHOTO 7: OILY WASTE IN COMPRESSOR SKID WITHOUT WILDLIKE PROTECTION NET OR SCREEN.

Corrective Action: DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181.

Date: 12/19/2025

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 291908 Lat: 37.093200 Long: -104.978300

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action

Date:

Fencing:

Fencing Type: None Fencing Condition: _____

Comment: _____

Corrective Action

Date:

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Corrective Action

Date:

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: _____

Corrective Action

Date:

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On THURSDAY 12-18-2025 at approximately 08:58, I Tom Beardslee Conducted an on-site inspection an Evergreen Natural Resources location APACHE CANYON 10-16V API# 05-071-07560 in Las Animas County Colorado. While there, I observed production operation. During this inspection the following possible compliance issues were observed: UNUSED EQUIPMENT, RULE 606, CA DATE 1-18-2026. IMPACTED SOIL, RULE 1002, (2).D. CA DATE 1-18-2026. OILY WASTE IN SKID, RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 12-19-2025. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	beardslit	12/18/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404479722	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7382491
716301892	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7382483
716301894	VACUUM SUNDRY	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7382484