

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 22B-1 Pad

Location #: 324253



Photo # 5618 From entrance to location




Photo # 5619 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 22B-1 Pad

Location #: 324253



Photo # 5620 Location



Photo # 5621 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 22B-1 Pad

Location #: 324253



Photo # 5622 Location



Photo # 5623 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 22B-1 Pad

Location #: 324253



Photo # 5624 Unused flowline lacks lockout tagout (OOSLAT)

Photo # 5625 Unused flowline lacks lockout tagout (OOSLAT)

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 22B-1 Pad

Location #: 324253



Photo # 5626 Methanol tank lacks required information

Photo # 5627 Methanol tank lacks required information

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 22B-1 Pad

Location #: 324253




Photo # 5628 Methanol tank lacks required information

Photo # 5629 Capacity on production tank weathered & starting to become illegible