

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/17/2025

Submitted Date:

12/22/2025

Document Number:

701104401

**FIELD INSPECTION FORM**

Loc ID 316215 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10844  
Name of Operator: QB ENERGY OPERATING LLC  
Address: 1001 17TH STREET SUITE 1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Energy, QB		ecmc.inspections@qb-energy.com	QB Inspection mail box

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257264	WELL	SI	09/01/2024	GW	103-10019	LOVE RANCH FEE 3	EG

**General Comment:**

Flowline Integrity Inspection / Follow up  
Corrective action from inspection 701104300 "Not all the information is correct: wrong Location id number (315635) lat/long not matching wellhead. No api # on sign. Install sign to comply with Rule 605.e. CA Date 11/28/2025"  
Location number was changed but with another wrong location id. # 335717.  
The location id # is 316215

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	Corrective action from inspection 701104300 "Not all the information is correct: wrong Location id number (315635) lat/long not matching wellhead. No api # on sign. Install sign to comply with Rule 605.e. CA Date 11/28/2025" Location number was changed but with another wrong location id. # 335717. The location id # is 316215		
Corrective Action:	Correct the location id on sign.	Date:	01/10/2026

**Emergency Contact Number:**

Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>	Date:	<input style="width: 100%;" type="text"/>

**Good Housekeeping:**

Type	TRASH		
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>	Date:	<input style="width: 100%;" type="text"/>

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No	<input style="width: 100%;" type="text"/>		
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>	Date:	<input style="width: 100%;" type="text"/>

**Flaring:**

Type	<input style="width: 100%;" type="text"/>		
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>	Date:	<input style="width: 100%;" type="text"/>

**Inspected Facilities**

Facility ID: 257264 Type: WELL API Number: 103-10019 Status: SI Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404484037	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7388144">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7388144</a>
701104403	Flowline integrity inspection 701104401 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7388142">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7388142</a>