

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT EMERALD #92X PAD

Location ID: 315816

Date: 12/15/2025



Photo # 0193 Entrance to location



Photo # 0194 Location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT EMERALD #92X PAD

Location ID: 315816

Date: 12/15/2025




Photo # 0195 Location



Photo # 0196 Sign lacks public road used to access the well.
No tank battery on location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT EMERALD #92X PAD

Location ID: 315816

Date: 12/15/2025



Photo # 0198 NW corner of location



Photo # 0199 NE corner of location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT EMERALD #92X PAD

Location ID: 315816

Date: 12/15/2025



Photo # 0200 SE corner of location



Photo # 0201 SW corner of location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT EMERALD #92X PAD

Location ID: 315816

Date: 12/15/2025



Photo # 0206 Lack of stabilization/Compaction on location



Photo # 0207 Lack of stabilization/Compaction on location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT EMERALD #92X PAD

Location ID: 315816

Date: 12/15/2025



Photo # 0208 Lack of stabilization/Compaction on location

Photo # 0209 Lack of stabilization/Compaction on location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT EMERALD #92X PAD

Location ID: 315816

Date: 12/15/2025



Photo # 0210 Entrance to location sign