

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/18/2025

Submitted Date:

12/29/2025

Document Number:

719700363

FIELD INSPECTION FORM

Loc ID 416142 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416170	WELL	PA	08/04/2025	OW	123-31301	WALCKER USX AB01-08P	PA

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type					corrective date
Pump Jack		# 0			
Comment:	Plugged & Abandoned PA. Equipment removed.				
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities					
Facility ID:	416170	Type:	WELL	API Number:	123-31301
Status:	PA	Insp. Status:	PA		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12					

ECMC Comments

Comment	User	Date
<p>CECMC Audit Report Synopsis:</p> <p>On THU 12/18/2025 at approximately 11:31 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: NOBLE ENERGY INC Location Name: WALCKER USX/AB01-08P Location ID: 416142 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this report. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Active. Active Battery SE corner GPS coordinates: 40.604375 / -104.497437</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Form 6-SRA on file. Plugging, cut/cap date: 08/04/2025. Approved. Plugged & Abandoned PA well GPS coordinates: 40.604180 / -104.489920 Form 19, Form 27 on file. Approved.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	12/29/2025
<p>This is a PLUGGED & ABANDONED WELL audit. Well(s): 1: Plugged & Abandoned PA. Battery: Active. Active Battery SE corner GPS coordinates: 40.604375 / -104.497437</p> <p>Centralized Battery serves 2 Location IDs (415995, 416249). (Well(s): 1: Producing PR, 1: Temporarily Abandoned TA).</p> <p>Centralized Battery formerly served 2 Location IDs (415959, 416142). (Well(s): 2: Plugged & Abandoned PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (491573).</p> <p>Reference (Associated Well(s), Battery Audits): A.) Field Audit Report doc. #719700359 and/or Location ID #415995 for PR Well(s) info. B.) Field Audit Report doc. #719700361 and/or Location ID #416249 for TA Well(s) info. C.) Field Audit Report doc. #719700363 and/or Location ID #416142 for PA Well(s) info. D.) Field Audit Report doc. #719700365 and/or Facility ID #491573 for Battery / Facility, Equipment info.</p>	evinsb	12/29/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700364	Audit photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7393930