

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC EMERALD #53X PAD

Location ID: 314841

Date: 12/15/2025



Photo # 2017 Entrance to location

Photo # 0220 Location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC EMERALD #53X PAD

Location ID: 314841

Date: 12/15/2025



Photo # 0221 Sign near wellhead lacks public road used to access the well

Photo # 0228 NE corner of location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC EMERALD #53X PAD

Location ID: 314841

Date: 12/15/2025



Photo # 0229 SE corner of location



Photo # 0230 SW corner of location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC EMERALD #53X PAD

Location ID: 314841

Date: 12/15/2025



Photo # 0231 NW corner of location



Photo # 0218 Sign at entrance to location contains previous operator name/not in compliance with CECMC rules