

# Inspection Photos

API: 071-08731

Operator: OGRIS OPERATING LLC

Inspection Date: 12/30/2025

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southeast at the PA'd wellsite. The pit has been backfilled and equipment is removed.



## Inspection Photos



**Photo 2.** Facing toward the northeast side of the location. There are signs of erosion along this area of the location and soils are not stabilized.



## Inspection Photos



**Photo 3.** Facing southwest at the location. The fill slope will need to be recontoured back into the original contours to comply with 1004 Rules.



## Inspection Photos



**Photo 4.** Drone aerial photo facing east overlooking the location.



## Inspection Photos



**Photo 5.** Drone aerial photo facing northeast overlooking the location.



## Inspection Photos



**Photo 6.** Drone aerial photo facing south. The fill slope material shown approximately to the left side of the line will need to be replaced back into the cut slope.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos



**Photo 7.** Drone aerial photo facing southwest.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-08731 | Date: 12/30/2025