

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/19/2025

Submitted Date:

12/31/2025

Document Number:

715203637

**FIELD INSPECTION FORM**

Loc ID 317311 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10536  
Name of Operator: SMITH ENERGY LLC  
Address: 1540 MAIN ST SUITE 218 #334  
City: WINDSOR State: CO Zip: 80550

**Findings:**

- 11 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Schure, Kym		kym.schure@state.co.us	
Smith, Chris	(303) 709-6157	smithenergy@live.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
238028	WELL	PR	04/01/2017	GW	121-10531	McCREATH 16-15	PR

**General Comment:**

SE Compliance Specialist Brian Welsh conducted a follow-up field inspection to previous inspection #715203442 on 11/19/25

Previous comment from last inspection on 11/19/25: Lease sign mounted to meter shed is faded and operator sticker has fallen off.  
Previous Corrective action from last inspection on 11/19/25: Install sign to comply with Rule 605.d.

Previous comment from last inspection on 11/19/25: Berms around the tank have eroded over time and are not visible at time of inspection.  
Pictures from inspection on 3/16/20 show berms were present during that inspection  
Previous Corrective action from last inspection on 11/19/25: Repair or install berms or other secondary containment devices per Rule 603.o.

Previous Corrective action dates from inspection on 11/19/25: 12/19/25

Corrective actions were not addressed at time of this inspection on 12/19/25

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track through pasture		
Corrective Action		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by buried tank		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease sign mounted to meter shed is faded and operator sticker has fallen off		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	12/19/2025

<b>Emergency Contact Number:</b>			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Metal panels around wellhead and chemical tank		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Wire fence around entire location at wellhead		
Corrective Action:		Date:	
Type	PIT		
Comment:	Meter shed, metal shed and pit are 3/4 fenced with wire		
Corrective Action:		Date:	

<b>Tanks and Berms:</b>						
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLs	PBV FIBERGLASS		39.876364,-102.953954	
Comment:	Fiberglass tank partially buried at southeast corner of pit					

Corrective Action:		Date:	
--------------------	--	-------	--

**Paint**

Condition	
Other (Content)	
Other (Capacity)	24bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate			
Comment:	Berms around the tank have eroded over time and are not visible at time of inspection. Pictures from inspection on 3/16/20 show berms were present during that inspection			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date: 12/19/2025

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 238028 Type: WELL API Number: 121-10531 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Meter shed is 660' NE of wellhead on west side of CR SS](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715203676	location photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7397632">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7397632</a>