

# Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC U P #97 X 29 PAD

Location ID: 314968

Date: 12/16/2025



Photo # 0269 Entrance to location



Photo # 0271 Location

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC U P #97 X 29 PAD

Location ID: 314968

Date: 12/16/2025



Photo # 0272 Wellhead sign lacks public road used to access the well

Photo # 0282 NW corner of location

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC U P #97 X 29 PAD

Location ID: 314968

Date: 12/16/2025



Photo # 0283 SW corner of location



Photo # 0284 SE corner of location

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC U P #97 X 29 PAD

Location ID: 314968

Date: 12/16/2025



Photo # 0285 NE corner of location



Photo # 0277 Loss of berm integrity due to erosion on north side of location/insufficient BMP's

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC U P #97 X 29 PAD

Location ID: 314968

Date: 12/16/2025



**Photo # 0279 Loss of berm integrity due to erosion on north side of location/insufficient BMP's**



**Photo # 0280 Loss of berm integrity due to erosion on north side of location/insufficient BMP's**

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC U P #97 X 29 PAD

Location ID: 314968

Date: 12/16/2025



**Photo # 0281 Loss of berm integrity due to erosion on north side of location/insufficient BMP's**

**Photo # 0286 Loss of berm integrity due to erosion on north side of location/insufficient BMP's**