

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC FEE #72X PAD

Location ID: 314767

Date: 12/16/2025



Photo # 0294 Sign at entrance to location



Photo # 0295 Entrance to location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC FEE #72X PAD

Location ID: 314767

Date: 12/16/2025



Photo # 0296 Location



Photo # 0297 Wellhead sign lacks public road used to access the well

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC FEE #72X PAD

Location ID: 314767

Date: 12/16/2025



Photo # 0304 NW corner of location



Photo # 0305 SW corner of location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC FEE #72X PAD

Location ID: 314767

Date: 12/16/2025



Photo # 0306 SE corner of location



Photo # 0307 NE corner of location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC FEE #72X PAD

Location ID: 314767

Date: 12/16/2025



Photo # 0300 Staining on location



Photo # 0301 Staining on location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC FEE #72X PAD

Location ID: 314767

Date: 12/16/2025



Photo # 0303 Staining on location



Photo # 0308 Debris on NE side of location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC FEE #72X PAD

Location ID: 314767

Date: 12/16/2025



Photo # 0310 Debris on NE side of location



Photo # 0311 Debris on NE side of location