

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC U P #96 X 29 PAD

Location ID: 314967

Date: 12/16/2025



Photo # 0320 Sign at entrance to location/sign contains previous operator name on top left corner.

Photo # 0321 Entrance to location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC U P #96 X 29 PAD

Location ID: 314967

Date: 12/16/2025



Photo # 0322 Location



Photo # 0323 Wellhead sign lacks public road used to access the well

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC U P #96 X 29 PAD

Location ID: 314967

Date: 12/16/2025



Photo # 0331 Location



Photo # 0332 SE corner of location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC U P #96 X 29 PAD

Location ID: 314967

Date: 12/16/2025



Photo # 0333 SW corner of location



Photo # 0334 NW corner of location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC U P #96 X 29 PAD

Location ID: 314967

Date: 12/16/2025



Photo # 0335 NE corner of location

Photo # 0341 Debris on north side of location

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC U P #96 X 29 PAD

Location ID: 314967

Date: 12/16/2025



Photo # 0342 Debris on north side of location