


Inspection Photos
Location Name: BLC 8-2A
Location ID: 331995



Production facility



Wellhead

Inspection Photos
Location Name: BLC 8-2A
Location ID: 331995



South crude oil tank fencing



East crude oil tank fencing

Inspection Photos
Location Name: BLC 8-2A
Location ID: 331995



North separator fencing



North-east separator fencing