

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/16/2025

Submitted Date:

01/03/2026

Document Number:

713401170

**FIELD INSPECTION FORM**

Loc ID 314967 Inspector Name: Popejoy, Dusty On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10779  
Name of Operator: SCOUT ENERGY MANAGEMENT LLC  
Address: 13800 MONTFORT DRIVE SUITE 100  
City: DALLAS State: TX Zip: 75240

**Findings:**

- 18 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Saint, John		jsaint@scoutep.com	
Wiley, Mikel		Mikel.Wiley@scoutep.com	
Rosado, Sydney		Sydney.Rosado@scoutep.com	
Sanford, Anita		anita.sanford@scoutep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229991	WELL	PR	01/01/2023	OW	103-07650	U P 96 X 29	PR

**General Comment:**

[This is a Field Inspection/audit of the scout card, related documents and the location.](#)

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Access		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	No tank battery on location		
Corrective Action:			Date:
Type	OTHER		
Comment:	Sign at entrance to location contains previous operator name on top left corner/No public road used to access the well information		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Wellhead sign lacks public road used to access the well. No tank battery on location.		
Corrective Action:	Comply with CECMC rule 605		Date: 02/03/2026
Emergency Contact Number:			
Comment:	970-675-3700/911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Debris on north side of location, refer to photos		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Ancillary equipment	# 1		corrective date
Comment:	Chemical tank		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is accessible/equipped with gauge - BH line tied into flowline		
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 229991 Type: WELL API Number: 103-07650 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 08/21/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 45 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: BH line tied into flowline FORM 4 SUNDRY document #404426609

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Light compaction
		Gravel				Sparse to none in most areas
		Ditches				
				Material Handling And Spill Prevention		Chemical tank containment 1/2 full of fluid
Gravel						Sparse to none in most areas
Berms						
		Compaction				Light compaction

Comment: Operator is responsible for maintaining Best Management Practices (BMP's) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><a href="#">CECMC Inspection/Audit Report Summary</a></p> <p>On 12/16/2025 at approximately 13:49 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at SCOUT ENERGY MANAGEMENT LLC U P #96 X 29 PAD at Location ID #314967 in Rio Blanco County, Colorado.</p> <p>This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations.</p> <p>While there, I observed normal production operations.</p> <p>During the inspection/audit, the following compliance issues were observed:</p> <p>1. Signs/Marker - Wellhead sign lacks public road used to access the well with a CA date of 02/03/2026</p> <p>Comments:</p> <p>1. Housekeeping - Debris on north side of location</p> <p>A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of inspection/audit report.</p>	popejoyd	01/03/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713401171	713401170 Inspection-Audit Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7401770">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7401770</a>