

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/04/2025

Submitted Date:

01/04/2026

Document Number:

711902811

**FIELD INSPECTION FORM**

Loc ID 428763 Inspector Name: SCHURE, KYM On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10322  
Name of Operator: EAST CHEYENNE GAS STORAGE LLC  
Address: 370 VAN GORDON STREET  
City: LAKEWOOD State: CO Zip: 80228

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Beem, Alex		alex.beem@tallgrass.com	Res. Engineer

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420118	WELL	AC	08/14/2014	STOW	075-09389	WP -D004-1	AC
438157	WELL	AC	11/13/2017	STOW	075-09426	WP -D004-2	AC

**General Comment:**

**THIS IS A FIELD AUDIT OF THE SCOUT CARD, RELATED DOCUMENTS AND LOCATION ROUTINE FIR - SATISFACTORY**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	GRAVEL TO GRAVEL		
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	SATISFACTORY		
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	SATISFACTORY		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No  
 Comment: NONE

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	SECURITY CHAIN LINK		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Other	# 0		
Comment:	NO CHANGE		
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 420118 Type: WELL API Number: 075-09389 Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 438157 Type: WELL API Number: 075-09426 Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
SATISFACTORY	schureky	01/04/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
711902829	PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7401707">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7401707</a>