

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/19/2025

Submitted Date:

12/31/2025

Document Number:

715203634

**FIELD INSPECTION FORM**

Loc ID 317174 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10536  
Name of Operator: SMITH ENERGY LLC  
Address: 1540 MAIN ST SUITE 218 #334  
City: WINDSOR State: CO Zip: 80550

**Findings:**

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Schure, Kym		kym.schure@state.co.us	
Smith, Chris	(303) 709-6157	smithenergy@live.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
237016	WELL	PR	04/01/2017	GW	121-09516	THIM 3-14	PR

**General Comment:**

SE Compliance Specialist Brian Welsh conducted a follow-up field inspection to previous inspection #715203441 on 11/19/25

Previous comment from last inspection on 11/19/25: Metal culvert buried inside pit area. The outline of the pit is not visible and sand has filled the pit over the years

Previous Corrective action from last inspection on 11/19/25: Clean out the area designated as the pit

Previous Corrective action date from inspection on 11/19/25: 12/19/25

Corrective action was not addressed at time of this inspection on 12/19/25

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track through pasture		
Corrective Action:		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by culvert		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease sign at meter shed		
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Tires are in place around meter shed and metal shed fencing to deter cattle		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 95%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Wire fence around meter shed, metal shed and culvert		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal panels around wellhead		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 237016 Type: WELL API Number: 121-09516 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Meter shed is 150' SW of wellhead](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						
Type: <u>Evaporation</u>	Lined: <u>NO</u>	Pit ID:	Lat: <u>39.875920</u>	Long: <u>-102.938430</u>		
Reference Point: <u>SE</u>	Other: _____	Length: <u>15</u>	Width: <u>20</u>			
<b>Lining:</b>						
Liner Type:			Liner Condition:			
Comment: <input style="width:95%;" type="text"/>						Date:
Corrective Action <input style="width:95%;" type="text"/>						
<b>Fencing:</b>						
Fencing Type: <u>Livestock</u>			Fencing Condition: <u>Adequate</u>			
Comment: <u>Wire fence around meter shed, metal shed and culvert</u>						Date:
Corrective Action <input style="width:95%;" type="text"/>						
<b>Netting:</b>						
Netting Type:			Netting Condition:			
Comment: <input style="width:95%;" type="text"/>						Date:
Corrective Action <input style="width:95%;" type="text"/>						
Anchor Trench Present:		Oil Accumulation:		2+ feet Freeboard:		
Comment: <u>Metal culvert buried inside pit area. The outline of the pit is not visible and sand has filled the pit over the years</u>						Date: <u>12/19/2025</u>
Corrective Action <u>Clean out the area designated as the pit</u>						

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404491037	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7397633">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7397633</a>
715203670	East side of culvert looking west on Dec 19th 2025	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7397626">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7397626</a>
715203671	East side of culvert looking west on Nov 19th 2025	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7397627">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7397627</a>