

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/19/2025

Submitted Date:

12/31/2025

Document Number:

715203636

FIELD INSPECTION FORM

Loc ID 317385 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10536
Name of Operator: SMITH ENERGY LLC
Address: 1540 MAIN ST SUITE 218 #334
City: WINDSOR State: CO Zip: 80550

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schure, Kym		kym.schure@state.co.us	
Smith, Chris	(303) 709-6157	smithenergy@live.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273532	WELL	PR	11/01/2016	GW	121-10789	THIM 8-14	PR

General Comment:

SE Compliance Specialist Brian Welsh conducted a follow-up field inspection to previous inspection #715203439 on 11/19/25
 Previous comment from last inspection on 11/19/25: Inspector only found 3 deamen and they were not marked
 Previous Corrective action from last inspection on 11/19/25: Locate and mark all deadmen
 Previous Corrective action date from inspection on 11/19/25: 12/19/25
 Corrective action was not addressed at time of this inspection on 12/19/25

Location			
Lease Road:			
Type	Access		
comment:	Access wellhead through corals of landowner		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	CONTAINERS		
Comment:	Sticker on chemical tank is faded and needs replaced		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Metal panels around wellhead and chemical drum		
Corrective Action:			Date:
Equipment:			
Type: Deadman # & Marked	# 3		corrective date
Comment:	Inspector only found 3 deamen and they were not marked		
Corrective Action:	Locate and mark all deadmen		Date: <u>12/19/2025</u>
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 273532 Type: WELL API Number: 121-10789 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Central meter run for \(THIM 4-14 & 8-18\) 930' SE at THIM 4-14](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass			Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404491038	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7397634
715203673	NW deadman not marked	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7397629
715203674	SE deadman not marked	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7397630
715203675	SW deadman not marked	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7397631