

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/19/2025

Submitted Date:

12/31/2025

Document Number:

715203637

FIELD INSPECTION FORM

Loc ID 317311 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10536
Name of Operator: SMITH ENERGY LLC
Address: 1540 MAIN ST SUITE 218 #334
City: WINDSOR State: CO Zip: 80550

Findings:

- 11 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|----------------|------------------------|---------|
| Schure, Kym | | kym.schure@state.co.us | |
| Smith, Chris | (303) 709-6157 | smithenergy@live.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 238028 | WELL | PR | 04/01/2017 | GW | 121-10531 | McCREATH 16-15 | PR |

General Comment:

SE Compliance Specialist Brian Welsh conducted a follow-up field inspection to previous inspection #715203442 on 11/19/25

Previous comment from last inspection on 11/19/25: Lease sign mounted to meter shed is faded and operator sticker has fallen off.
Previous Corrective action from last inspection on 11/19/25: Install sign to comply with Rule 605.d.

Previous comment from last inspection on 11/19/25: Berms around the tank have eroded over time and are not visible at time of inspection.

Pictures from inspection on 3/16/20 show berms were present during that inspection
Previous Corrective action from last inspection on 11/19/25: Repair or install berms or other secondary containment devices per Rule 603.o.

Previous Corrective action dates from inspection on 11/19/25: 12/19/25

Corrective actions were not addressed at time of this inspection on 12/19/25

Location

| | | | |
|--------------------|---------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Two track through pasture | | |
| Corrective Action | | Date: | |

Overall Good:

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Lease sign by wellhead | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Metal sign by buried tank | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Lease sign mounted to meter shed is faded and operator sticker has fallen off | | |
| Corrective Action: | Install sign to comply with Rule 605.d. | Date: | 12/19/2025 |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|--------------------|---|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Metal panels around wellhead and chemical tank | | |
| Corrective Action: | | Date: | |
| Type | LOCATION | | |
| Comment: | Wire fence around entire location at wellhead | | |
| Corrective Action: | | Date: | |
| Type | PIT | | |
| Comment: | Meter shed, metal shed and pit are 3/4 fenced with wire | | |
| Corrective Action: | | Date: | |

| | | | | | | |
|-------------------------|---|----------|----------------|---------|-----------------------|--|
| Tanks and Berms: | | | | | | |
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | <50 BBLs | PBV FIBERGLASS | | 39.876364,-102.953954 | |
| Comment: | Fiberglass tank partially buried at southeast corner of pit | | | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Paint

| | |
|------------------|-------|
| Condition | |
| Other (Content) | |
| Other (Capacity) | 24bbl |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|---|---------------------|---------------------|------------------|
| Earth | Inadequate | | | |
| Comment: | Berms around the tank have eroded over time and are not visible at time of inspection. Pictures from inspection on 3/16/20 show berms were present during that inspection | | | |
| Corrective Action: | Repair or install berms or other secondary containment devices per Rule 603.o. | | | Date: 12/19/2025 |

Venting:

| | | |
|--------------------|--|-------|
| Yes/No | | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 238028 Type: WELL API Number: 121-10531 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Meter shed is 660' NE of wellhead on west side of CR SS](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | Material Handling And Spill Prevention | Pass | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 404491039 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7397635 |
| 715203676 | location photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7397632 |