

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Good Housekeeping:

Type	WEEDS		
Comment:	Weed debris at wellhead.		
Corrective Action:	Remove weeds to comply with Rule 606.	Date:	01/09/2026

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

				corrective date
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:		Date:		

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.276390,-104.895990
Comment:					
Corrective Action:				Date:	

Paint

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 411849 Type: WELL API Number: 123-30275 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>This is a corrective action Wellhead audit. Weed debris at wellhead. Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect.</p>	carlilec	12/31/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404490869	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7397510
716202247	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7397505