

# Inspection Photos

Loc: 324797

Operator: WESTERN OPERATING COMPANY

Inspection Date: 1/5/2026

County: KIOWA



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southwest toward the Dawson A 1 tank battery.



## Inspection Photos



**Photo 2.** Facing northeast at the tank battery. There are still oily impacts shown at red arrow on the soil surface.



## Inspection Photos



**Photo 3.** Facing east toward the remediation excavation area. Remediation remains in process and has been ongoing since 2022. There is undesirable weed debris accumulated inside the excavation.



## Inspection Photos



**Photo 4.** Facing southeast adjacent to the tank battery. This area disturbance needs to be reclaimed as it does not appear to be under active remediation.



## Inspection Photos



**Photo 5.** Facing toward the soil piles which have not been stabilized and weeds have not been controlled.



## Inspection Photos



**Photo 6.** Drone aerial photo facing west toward the tank battery and wellsite. Remediation remains in process and has been ongoing since 2022.



## Inspection Photos



**Photo 7.** West side of the location facing east overlooking the remediation area and tank battery.

