

Inspection Photos

Location Name: Kinder Morgan Doe Canyon Unit DC #6

API #: 05-033-06134

Inspector: Jamie Blair. Inspection Date: 01/02/2026

For Inspection Doc ID # 7211000044



01. Access to Kinder Morgan Well DC #6. The road condition was acceptable.

02. Well sign for Kinder Morgan DC #6. The sign lacks an API number. Include API Number next time sign is updated.

Inspection Photos

Location Name: Kinder Morgan Doe Canyon Unit DC #6

API #: 05-033-06134

Inspector: Jamie Blair. Inspection Date: 01/02/2026

For Inspection Doc ID # 7211000044



03. Kinder Morgan DC #6 well head assembly and meter run.

04. DC #6 well pad looking east.

Inspection Photos

Location Name: Kinder Morgan Doe Canyon Unit DC #6

API #: 05-033-06134

Inspector: Jamie Blair. Inspection Date: 01/02/2026

For Inspection Doc ID # 7211000044



05. Kinder Morgan DC #6, looking south.

06. DC #6 well cellar. Cellar is half full of water. Bradenhead access appears to be inside of PVC pipe.