

Inspection Photos

API:061-06010

Operator: WESTERN OPERATING COMPANY

Inspection Date: 1/5/2026

County: KIOWA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north toward the access road which will need to be recontoured and reclaimed.



Inspection Photos



Photo 2. Facing north toward the former tank battery location. Reclamation has not been performed.



Inspection Photos



Photo 3. There is a metal flowline culvert that needs to be removed. Flowlines must be abandoned per 1100 rules.



Inspection Photos



Photo 4. Facing northeast toward the wellsite location. There is erosion in this area beginning to occur.



Inspection Photos



Photo 5. Drone aerial photo facing north toward the access road and location.



Inspection Photos




Photo 6. Drone aerial photo overlooking the location disturbance.



Inspection Photos




Photo 7. Drone aerial photo facing south. There are impacted soils shown at red arrows from historical spill.



Inspection Photos



Photo 8. Drone aerial photo facing southeast. There are impacted soils shown at red arrow from historical spill.

