

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/07/2026

Submitted Date:

01/07/2026

Document Number:

715801810

**FIELD INSPECTION FORM**

Loc ID 321356 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

- 11 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206765	WELL	PA	07/12/2013	GW	013-06260	QUINBY MD 12-7J	PA
463943	OFF-LOCATION FLOWLINE	AC	04/19/2021		-	Wellhead Line 12SWNE	AC
463944	OFF-LOCATION FLOWLINE	AC	04/19/2021		-	Wellhead Line 12SWNE	AC
463945	OFF-LOCATION FLOWLINE	AC	04/19/2021		-	Wellhead Line 12SWNE	AC
463946	OFF-LOCATION FLOWLINE	AC	04/19/2021		-	Wellhead Line 12SWNE	AC
463947	OFF-LOCATION FLOWLINE	AC	04/19/2021		-	Wellhead Line 12SWNE	AC

**General Comment:**

[This is a field audit of the scout card, related documents and the location.](#)

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Wood & metal post with barb wire.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Wood & metal post with barb wire.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:	Card indicates current calibration.		
Corrective Action:		Date:	
Type: Flow Line	# 5		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		

Comment: <a href="#">automation &amp; telemetry</a>		Date:
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:		Date:
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV CONCRETE		
Comment:					Date:
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	60 bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment: <a href="#">Shares containment with crude tank.</a>				Date:
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		39.982300,-105.058600
Comment:					Date:
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				Date:
Corrective Action:				Date:

**Wells Served By Facilities Above**

API Number
013-06348
013-06374
013-06346

**AirsID**

API Number	AirsID
------------	--------

013-06351

013-06464

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 206765 Type: WELL API Number: 013-06260 Status: PA Insp. Status: PA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: The Tank battery serves wells that havent been PA & is on a location where the well has been PA since 7-12-2013 with no Facility ID, & still shows old operator information on the Scout card.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 463943 Type: OFF- API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 463944 Type: OFF- API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 463945 Type: OFF- API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 463946 Type: OFF- API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 463947 Type: OFF- API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Routine Audit/Inspection</a> Any corrective actions from previous Inspections that have not been addressed are still applicable Weather: Cloudy Temperature: 64* Location: Dry.	revasr	01/07/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715801811	Location photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7406412">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7406412</a>