

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/08/2026

Submitted Date:

01/08/2026

Document Number:

716301926

FIELD INSPECTION FORM

Loc ID 308665 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Findings:

- 10 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|--------------|-------------------|---------------------------------|
| BACA, DAVE | 719-859-4066 | dbaca@ogrisop.com | All Inspections |
| B WARD, GIENA | | gward@ogrisop.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 278286 | WELL | PR | 11/19/2018 | CBM | 071-08417 | GOLDEN EAGLE 21-10 | PR |

General Comment:

"This is a field audit of the scout card, related documents and the location."

Location

Overall Good:

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | | | |
| Comment: | API # IS NOT POSTED ON WELL SIGN AND CONTACT PHONE NUMBER IS FADED AND NOT LEGIBLE. | | |
| Corrective Action: | POST SIGN PER RULE 605. | Date: | 02/08/2026 |

| | | | |
|---------------------------|----------------------|--|----------------------------|
| Emergency Contact Number: | | | |
| Comment: | <input type="text"/> | | |
| Corrective Action: | <input type="text"/> | | Date: <input type="text"/> |

| | | | |
|---------------------------|--|-------|------------|
| Good Housekeeping: | | | |
| Type | OTHER | | |
| Comment: | PHOTO 6: There is oily fluids in the engine skid and stained material at the engine exhaust pipe. | | |
| Corrective Action: | Conduct maintenance on equipment, cleanup stained material and review self inspection processes. THIS IS THE SECOND NOTICE FOR THIS CA IMMEDIATE ACTION IS REQUIRED. | Date: | 01/08/2026 |
| Type | OTHER | | |
| Comment: | PHOTO 5: There is a dripping leak at the wellhead and a pool of water at wellhead with an oily sheen. | | |
| Corrective Action: | Control and contain spills/releases and clean up per Rule 912.a. THIS IS THE SECOND NOTICE FOR THIS CA IMMEDIATE ACTION IS REQUIRED. | Date: | 01/08/2026 |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|---------------------------|----------------------|--|----------------------------|
| Equipment: | | | corrective date |
| Type: Ancillary equipment | # 1 | | |
| Comment: | <input type="text"/> | | |
| Corrective Action: | <input type="text"/> | | Date: <input type="text"/> |
| Type: Prime Mover | # 1 | | |
| Comment: | <input type="text"/> | | |
| Corrective Action: | <input type="text"/> | | Date: <input type="text"/> |
| Type: Progressive Cavity | # 1 | | |
| Comment: | <input type="text"/> | | |
| Corrective Action: | <input type="text"/> | | Date: <input type="text"/> |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | <input type="text"/> | | |
| Corrective Action: | <input type="text"/> | | Date: <input type="text"/> |
| Type: Vertical Separator | # 1 | | |

| | | | |
|---------------------|---|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | IS ACCESSABLE | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR. | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 278286 Type: WELL API Number: 071-08417 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/18/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

| Permit: | Facility ID | Permit Num | Expiration Date |
|---------|-------------|------------|-----------------|
| | 292631 | 2059143 | |

ECMC Comments

| Comment | User | Date |
|---|----------|------------|
| <p>ECMC Inspection Report Summary</p> <p>On Thursday 1-8-2026 at approximately 13:02, I Tom Beardslee Conducted an on-site inspection an Ogris Operating LLC.10758 location GODEN EAGLE 21-10 API# 05-071-08417 in Las Animas County. While there, I observed production operation. During this inspection the following possible compliance issues were observed: PHOTO 2: API # IS NOT POSTED ON WELL SIGN AND CONTACT PHONE NUMBER IS FADED AND NOT LEGIBLE. POST SIGN PER RULE 605. CA DATE 2/8/2026. PHOTO 5: There is a dripping leak at the wellhead and a pool of water at wellhead with an oily sheen. PHOTO 6: There is oily fluids in the engine skid and stained material at the engine exhaust pipe. Control and contain spills/releases and clean up per Rule 912.a. THIS IS THE SECOND NOTICE FOR THIS CA IMMEDIATE ACTION IS REQUIRED. A follow-up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p> | beardslt | 01/08/2026 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------|---|
| 716301927 | insp. photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7408260 |