

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/08/2026

Submitted Date:

01/08/2026

Document Number:

716301934

FIELD INSPECTION FORM

Loc ID 333863 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 12 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
BACA, DAVE	719-859-4066	dbaca@ogrisop.com	All Inspections
B WARD, GIENA		gward@ogrisop.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271290	WELL	PR	10/01/2025	CBM	071-07994	GOLDEN EAGLE 21-3	PR
275200	WELL	PR	07/01/2012	CBM	071-08279	GOLDEN EAGLE 21-03CH	PR

General Comment:

[BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.](#)

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type			
Comment:	PHOTO 2: API # IS NOT POSTED ON EITHER WELL SIGNS.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	PHOTO 6: DEBRIS AROUND PIT (OLD ROTTING LOG FENCE).		
Corrective Action:	REMOVE ALL DEBRIS PER RULE 606.		Date: <u>01/20/2026</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
			corrective date
Type: Bradenhead	# 2		
Comment:	BOTH ARE ACCESSABLE		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:			Date:
Type: Progressive Cavity	# 2		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	25 BBL PRODUCED WATER/ USED OIL TANK		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:			Date:

Type: Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	PHOTO 5: CH WELLHEAD AND EQUIPMENT./ Vacuum pump observed on CH well without ECMC approval.		
Corrective Action:	Provide ECMC with documentation showing approval of use of vacuum pump.	Date:	01/26/2026

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 271290 Type: WELL API Number: 071-07994 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/26/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 275200 Type: WELL API Number: 071-08279 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/26/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 292703 Lat: 37.161440 Long: -104.895600

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: None Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date: _____

Permit:	Facility ID	Permit Num	Expiration Date
	292703	2059216	
	292703	2059216	

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Thursday 1/8/2026 at approximately 14:47, I Tom Beardslee Conducted an on-site inspection an Ogris Operating LLC.10758 location GOLDEN EAGLE 21-03 & CH API# 05-071-07994 in Las Animas County. While there, I observed production operation. During this inspection the following possible compliance issues were observed:PHOTO 2: API # IS NOT POSTED ON EITHER WELL SIGNS. PHOTO 5: CH WELLHEAD AND EQUIPMENT./ Vacuum pump observed on CH well without ECMC approval. Provide ECMC with documentation showing approval of use of vacuum pump. CA DATE 1/26/2026. PHOTO 6: DEBRIS AROUND PIT (OLD ROTTING LOG FENCE). REMOVE ALL DEBRIS PER RULE 606. CA DAT 1/20/2026.</p> <p>A follow-up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	beardslt	01/08/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716301935	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7408263