

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/08/2026

Submitted Date:

01/08/2026

Document Number:

708908209

FIELD INSPECTION FORM

Loc ID 335090 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1700 LINCOLN ST STE 3950
City: DENVER State: CO Zip: 80203

Findings:

- 19 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
LARAMIE ENERGY		cogccnotifications@laramie-energy.com	
Katz, Aaron		aaron.katz@state.co.us	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260063	WELL	PR	02/13/2005	GW	045-07811	CASCADE CREEK 629-31-11	PR
282707	WELL	PR	10/23/2018	GW	045-11816	CASCADE CREEK 697-29-15DX	PR
282708	WELL	PR	07/01/2020	GW	045-11815	CASCADE CREEK 697-29-20D	PR
284454	WELL	PR	08/24/2006	GW	045-12181	CASCADE CREEK 697-29-22D	PR

General Comment:

[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Sign at start of spur road to location		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:	911/1-800-891-6191		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:			Date:

Type: Dehydrator	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 4		
Comment:	Taylor plugs located on surface casing bradenheads, surface casing bradenhead valves are accessible		
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	<p>Mechanical Condition - Possible leak on tank valve</p> <p>At approximately 14:44 hours observed a possible leak on tank valve. At approximately 14:45 hours I called Matt Smelser with Laramie Energy & informed him about the leak & that I was issuing a 24 hour corrective action on the observed compliance issue. He told me they'd get it taken care of & then at approximately 15:00 hours he texted that someone was on the way to location to fix the issue.</p>		
Corrective Action:	Comply with CECMC Rule 608		Date: 01/09/2026

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
------	--

Comment:	
Corrective Action:	Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Sediment Traps				
		Rip Rap				
		Gravel				Sparse to none
		Ditches				
		Compaction				Light compaction in some sections
Gravel						Sparse to none in some areas
Compaction						Light compaction
Waddles						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary On 01/08/2026 at approximately 14:41 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection/audit at LARAMIE ENERGY LLC CC 0629-31-11 Pad Location # 335090 in Garfield County Colorado. Please refer to inspection/audit 713400629 conducted on 01/14/2025, previous corrective actions have been completed. Location is within High Priority/Density/NSO/Black Bear Habitat areas. Location is approximately 46 yards from Conn Creek. While there, I observed normal production operations.</p> <p>During this inspection/audit the following compliance issues were observed:</p> <ol style="list-style-type: none"> 1. Equipment - Mechanical Condition - Possible leak on tank valve - Comply with Rule 608 with a CA date of 01/09/2026 2. Inspected Facilities - Failure to comply with CECMC bradenhead monitoring, testing & reporting rules (CASCADE CREEK 697-29-15DX well) - Comply with Rule 419 with a CA date of 01/18/2026 3. Inspected Facilities - CASCADE CREEK 629-31-11 well lacks wellbore diagram - Comply with Rule 420 with a CA date of 02/07/2026 <p>A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This is a summary of inspection/audit report.</p>	smelserw	01/08/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708908211	Inspection/Audit 708908209 Leak Video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7408761

708908212	Inspection/Audit 708908209 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7408762
708908213	Inspection/Audit 708908209 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7408763