

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 22B-7 (Mesa 23)

Location #: 334728




Photo # 7664 From entrance to location

Photo # 7665 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 22B-7 (Mesa 23)

Location #: 334728



Photo # 7666 Location



Photo # 7667 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 22B-7 (Mesa 23)

Location #: 334728



Photo # 7668 Location



Photo # 7669 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 22B-7 (Mesa 23)

Location #: 334728



Photo # 7670 Open ended load line



Photo # 7671 Open ended load line

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 22B-7 (Mesa 23)

Location #: 334728



Photo # 7672 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 7673 Rupture disc vent line does not comply with CECMC pressure safety device rules