

FORM
INSPRev
X/20

State of Colorado

Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/31/2025

Submitted Date:

01/02/2026

Document Number:

718101040

FIELD INSPECTION FORM

Loc ID 314354 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10605
 Name of Operator: APEX OIL VENTURES INC
 Address: 8823 S. REDWOOD ROAD #D-1
 City: WEST JORDAN State: UT Zip: 84088

Findings:

6 Number of Comments
1 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
		t.rasmussen1@outlook.com	
		andy@qualityoilproperties.com	
		jec-apex@outlook.com	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Roberts, James		j75rober@blm.gov	Rio Blanco, Moffat
Katz, Aaron		aaron.katz@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228525	WELL	TA	04/01/2024	GW	103-05400	P.R.-TRIGOOD-GOV'T (0365) 10	RI
314354	LOCATION	AC			-	P.R.-TRIGOOD-GOV'T (0365)-61N101W 4NWSE	RI

General Comment:

On 12/31/2025, Western Reclamation Work Lead Trujillo conducted a Final Reclamation inspection at Apex Oil Ventures Inc's P.R.-TRIGOOD-GOV'T (0365) 10 location in Rio Blanco County, Colorado.

Location is Fed Surface, Fed Minerals

Location is within the following High Priority Habitats: Elk Severe Winter Range; Mule Deer Severe Winter Range; Mule Deer Winter Concentration Area.

This inspection is in response to Form 4 #404472977 stating "Final Reclamation Complete". It was observed in this inspection that Final Reclamation is not "Complete" pursuant to Rule 1004.c.

The following compliance issues were observed during this inspection:

-Facility Closure / Form 27 requirements

Refer to the Reclamation and Remediation sections of this inspection report for additional details.

Refer to the photo-documentation attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

Inspected Facilities

Facility ID: 228525 Type: WELL API Number: 103-05400 Status: TA Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 314354 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spill/Remediation:

Comment: Multiple, active and "in process" remediation projects exist on the Location for facility closure:

Operator submitted Form 27(i) #403875181 (Rem. Proj. #37651) for the decommissioning of Well 103-05400 and Off-Location Flowline Facility #477197 on 8/5/2024. Form was approved 10/30/2024 with the following COA:

-Assess the nature and extent of contamination with confirmation soil samples. Delineate the horizontal and vertical extent of impacted area and remediate impacts to Table 915-1

Operator submitted Form 27(i) #403975609 (Rem. Proj. #38103), also for the decommissioning of Well 103-05400 on 10/30/2024. Form was approved 12/4/2024 with the following COA:

-Operator shall address Arsenic exceedances.

A third Form 27(i) has since been submitted (#404473081, 12/15/2025), also for the decommissioning of Well 103-05400. This Form is currently in process.

No subsequent Form 27(s) has been filed. Ongoing remediation efforts on the Location do not appear to be occurring and initial 1004 Final Reclamation has since been performed (see "Final Reclamation").

Including area EPS on FIR for notification purposes.

Corrective Action: **Contact area EPS regarding Remediation Proj. Nos. 37651 and 38103.**

Comply with all outstanding COAs provided on an approved Form 27 or Form 4.

Comply with Rule 913.e reporting requirements.

Date: 01/09/2026

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged In Pit mouse/rat holes, cellars backfilled _____

Debris removed Pass No disturbance /Location never built _____

Access Roads Regraded Pass Contoured Pass Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured Pass

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% In Cropland: perennial forage _____

Weeds present In Process Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

It was observed in this inspection that reclamation of the Location and access road has been performed, though not "complete" pursuant to Rule 1004.c; location/road has been recontoured/regraded. Compaction alleviation appears to have been performed, though it is unclear if Location has been "cross-ripped" pursuant to Rule 1003.c.

Remediation Proj. Nos. 37651 and 38103 for facility closure on the Location remain active and in process. Any reclamation work performed has been done so "at risk", as work that could be necessary to resolve the remediation projects may result in redisturbance of the reclaimed areas

Corrective Action:

Date

Overall Final Reclamation

In Process

Well Release on Active Location

Multi-Well Location

ECMC Comments

Comment	User	Date
Note to Operator: Form 6(s) #403930660 remains "in process" at time of writing FIR. Including ECMC Engineering Group for notification purposes. Advise contacting area Engineer regarding form resolution.	trujilloam	01/02/2026
No Form 42- Notice of Plugging Operations was filed pursuant to Rule 405.I prior to plugging and abandonment of the well.	trujilloam	01/02/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404495090	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7402676
718101042	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7401739