

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/08/2026

Submitted Date:

01/10/2026

Document Number:

720900534

**FIELD INSPECTION FORM**

Loc ID 304806 Inspector Name: St John, William (Cal) On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

23 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**

ECMC Operator Number: 66190  
Name of Operator: OMIMEX PETROLEUM INC  
Address: 100 CRESCENT CT SUITE700-#5528  
City: DALLAS State: TX Zip: 75201

**Contact Information:**

Contact Name	Phone	Email	Comment
De Paolo, Corey		corey.depaolo@state.co.us	
Reinhardt, Kelley		kelley.reinhardt@state.co.us	OWP
Hickey, Mike		michael.hickey@state.co.us	OWP
Abrahms, Deborah		deborah.abrams@state.co.us	OWP

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275187	WELL	PR	02/01/2022	GW	125-09008	BLEDSOE 7-31-3-43 (OWP)	SI

**General Comment:**

This is an Orphaned Well Program (OWP) well location inspection placing emphasis on detection of fluid/gas release, equipment inventory, and location safety/security.

On 01/08/2026 at approximately 1:15 PM inspector arrived at location and discovered tubing joint had pushed estimated 25-28 feet out of the wellbore. No master valve on wellhead tree.

Notified OWP East Team via text message at 1:35 PM.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Two track off maintained County Road. Sandy final approach into well location.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Old operator sign at wellhead.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	No current emergency contact information at well location.		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Production related debris at well location. Wooden cribbing outside well fencing.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Stock panel fencing around surface equipment at well location.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bradenhead	# 0		corrective date
Comment:	Bradenhead not visible at surface.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Chart Recorder.		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Sentry. Horsehead and bridle removed and inside wellhead fencing.		

Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	2-Phase vertical separator.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Pump Jack Cement Pad.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	Flowline riser at wellhead with valve. Valve open ended. Possible water line.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Rods removed. Unknown tubing sting length in the wellbore. Casing valve closed. Open ended valve on welltree.  Tubing has pushed up out of wellbore estimated 25-28 feet.		
Corrective Action:		Date:	
Type: Prime Mover	# 0		
Comment:	Removed.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Steel Separator/Meter Shed inside wellhead fencing.		
Corrective Action:		Date:	

**Venting:**

Yes/No	YES		
Comment:	Well is leaking gas at the tubing hanger to casing seals.		
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Location Construction**

Location ID: 275187 CDP: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** No COA's.

Corrective Action:

Date: \_\_\_\_\_

**Wildlife BMPs:**

**Comment:**

Corrective Action:

Date: \_\_\_\_\_

**Comment:**

**Corrective Action:**

Date: \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Inspected Facilities**

Facility ID: 275187 Type: WELL API Number: 125-09008 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Operator no longer active in the State of Colorado. Well has been moved into OWP. Tubing string valve closed. Casing valve closed.

Electronic Well File reflects last Production/Status reported 08/01/2022 and Well Status as PR. Based on current valve settings at time of inspection the well is SI. SI date unknown.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
Produced water. No battery at well location. FIR completed 1/11/2006 document number 200083721 states - Water to the injection well thru a flowline. Injection well Bledsoe SWD #1-18-3-43 API 05-125-09352. Injection well is north of well location and is approximately 3.25 miles.	stjohnw	01/10/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
720900535	Audit Photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7410639">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7410639</a>
720900536	Wellhead video.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7410640">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7410640</a>