

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 11A-18D (Mesa 3)

Location # 334704



Photo # 8100 From entrance to location




Photo # 8101 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 11A-18D (Mesa 3)

Location # 334704



Photo # 8102 Location



Photo # 8103 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 11A-18D (Mesa 3)

Location # 334704




Photo # 8104 Location



Photo # 8105 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 11A-18D (Mesa 3)

Location # 334704



Photo # 8106 Location



Photo # 8107 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 11A-18D (Mesa 3)

Location # 334704



Photo # 8108 Unused equipment



Photo # 8109 Open ended load line

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 11A-18D (Mesa 3)

Location # 334704



Photo # 8110 Barbed wire fence needs maintenance/wildlife hazard



Photo # 8111 Barbed wire fence needs maintenance/wildlife hazard

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 11A-18D (Mesa 3)

Location # 334704



Photo # 8112 Barbed wire fence needs maintenance/wildlife hazard