

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/06/2026

Submitted Date:

01/10/2026

Document Number:

708908239

**FIELD INSPECTION FORM**

Loc ID 335170 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 25 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
TEP		ECMCInspectionReports@flywheelenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210792	WELL	PR	12/02/1987	GW	045-06550	CHEVRON MV-22-20	PR
283746	WELL	PR	09/05/2006	GW	045-11992	CHEVRON GM 443-20	PR
283750	WELL	PR	03/10/2006	GW	045-11989	CHEVRON GM 533-20	PR
283751	WELL	PR	03/10/2006	GW	045-11990	CHEVRON GM 543-20	PR
283752	WELL	PR	03/10/2006	GW	045-11991	CHEVRON GM 433-20	PR

**General Comment:**

[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No \_\_\_\_\_

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	Air compressors - hog panels		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:

Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 5		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:	Marked		
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	CHEVRON GM 533-20 & CHEVRON GM 543-20 wells have no form of pressure monitoring equipment located on bradenheads, bradenhead valves are accessible.  CHEVRON MV-22-20, CHEVRON GM 443-20 & CHEVRON GM 433-20 wells have Taylor plugs located on bradenheads, bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 9		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Air compressors		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 9		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:					Date:

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Inadequate	Walls Sufficient	Base Insufficient	Inadequate

Comment:		Hole in secondary containment liner/liner needs maintenance				Date:		01/30/2026
Corrective Action:		Comply with CECMC Rule 603				Date:		01/30/2026
Contents	#	Capacity	Type	Tank ID	SE GPS			
PRODUCED WATER	1	200 BBLs	STEEL AST		,			
Comment:		Tank equipped with telemetry				Date:		
Corrective Action:						Date:		
<b>Paint</b>								
Condition	Adequate							
Other (Content)								
Other (Capacity)								
Other (Type)								
<b>Berms</b>								
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance				
Metal								
Comment:		Centralized containment				Date:		
Corrective Action:						Date:		
<b>Venting:</b>								
Yes/No	NO							
Comment:								
Corrective Action:					Date:			
<b>Flaring:</b>								
Type								
Comment:								
Corrective Action:					Date:			

Inspected Facilities									
Facility ID:	210792	Type:	WELL	API Number:	045-06550	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	283746	Type:	WELL	API Number:	045-11992	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	283750	Type:	WELL	API Number:	045-11989	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	283751	Type:	WELL	API Number:	045-11990	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	283752	Type:	WELL	API Number:	045-11991	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Compaction						Small amount of light compaction
		Ditches				
Gravel						Sparse to none in most areas
		Gravel				Sparse to none in areas
		Compaction				Small amount of light compaction

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary                      On 01/06/2026 at approximately 10:44 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection/audit at TEP ROCKY MOUNTAIN LLC CHEVRON MV-22-20 Pad                      Location # 335170 in Garfield County Colorado.                      Location is within High Priority/Density/NSO/Black Bear Habitat areas.                      Location is approximately 129 yards from Parachute Creek.                      While there, I observed normal production operations.</p> <p>During this inspection/audit the following compliance issues were observed:</p> <p>1. Tanks &amp; Berms - Hole in secondary containment liner/liner needs maintenance - Comply with Rule 603 with a CA date of 01/30/2026</p> <p>Split pad/remote location - Shared facilities with the CHEVRON GM 44-20 Pad location # 335419</p> <p>A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.                      This is a summary of inspection/audit report.</p>	smelserw	01/10/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708908240	Inspection/Audit 708908239 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7410831">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7410831</a>
708908241	Inspection/Audit 708908239 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7410832">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7410832</a>