

Inspection Photos
Location Name: Williams 14-21
API Number: 125-07897



1. Lease sign at well location.



2. View of wellhead. Well was discovered leaking at packing. Leak has been repaired . Lease Operator will clean up and turn soil around wellhead.

Inspection Photos
Location Name: Williams 14-21
API Number: 125-07897



3. View of flowline risers at well location. Note open ended valve.




4. View of Separator/Meter Shed at well location.

Inspection Photos
Location Name: Williams 14-21
API Number: 125-07897



5. Gas Meter inside Meter Shed.



6. Well location overview.