

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/08/2026

Submitted Date:

01/11/2026

Document Number:

708908242

FIELD INSPECTION FORM

Loc ID 335150 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1700 LINCOLN ST STE 3950
City: DENVER State: CO Zip: 80203

Findings:

21 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Katz, Aaron		aaron.katz@state.co.us	
LARAMIE ENERGY		cogccnotifications@laramie-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276501	WELL	PR	01/25/2013	GW	045-10477	CASCADE CREEK 697-20-28	PR
281808	WELL	PR	08/30/2006	GW	045-11546	CASCADE CREEK 697-20-34D	PR
281809	WELL	PR	10/23/2018	GW	045-11547	CASCADE CREEK 697-20-26D	PR
281810	WELL	PR	10/23/2018	GW	045-11549	CASCADE CREEK 697-20-36D	PR
283068	WELL	PR	07/18/2011	GW	045-11894	CASCADE CREEK 697-20-21D	PR

General Comment:

[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Sign at start of spur road to location		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911/1-800-891-6191		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	TANK BATTERY		
Comment:	Pipe rail fence		
Corrective Action:			Date:

Equipment:			corrective date
Type: Dehydrator	# 3		
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	CASCADE CREEK 697-20-21D well has no form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible. Remaining 4 wells have Taylor plugs located on bradenheads, bradenhead valves are accessible		
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		
Comment:	Tank equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	

Corrective Action:

Date:

Inspected Facilities

Facility ID: 276501 Type: WELL API Number: 045-10477 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 281808 Type: WELL API Number: 045-11546 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 07/02/2025 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 230 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: 0 psi differential between SC & PC at start of most recent BH test

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 281809 Type: WELL API Number: 045-11547 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 281810 Type: WELL API Number: 045-11549 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 283068 Type: WELL API Number: 045-11894 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				Sparse to none
Berms						
Ditches						
		Compaction				Light compaction in some sections
Other						Rill erosion developing on cut slope near battery
		Culverts				
Compaction						Light compaction in some areas
Check Dams						
		Rip Rap				
		Ditches				
		Sediment Traps				
Other						Concrete barriers

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary On 01/08/2026 at approximately 11:46 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection/audit at LARAMIE ENERGY CC 0697-20-28 Pad Location # 335150 in Garfield County Colorado. Location is within High Priority/Density/NSO/Black Bear Habitat areas. Location is approximately 140 yards from Conn Creek. While there, I observed normal production operations.</p> <p>This is a summary of inspection/audit report.</p>	smelserw	01/11/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708908243	Inspection/Audit 708908242 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7411092
708908244	Inspection/Audit 708908242 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7411093