

**Inspection Photos**  
**Location Name: Williams 24-21**  
**API Number: 125-09062**



**1. Lease sign at well location.**



**2. View of wellhead. Note one of the three risers at well location right of frame.**

**Inspection Photos**  
**Location Name: Williams 24-21**  
**API Number: 125-09062**



**3. Gas Meter inside Flowline mounted Meter Box.**



**6. Well location overview.**

**Inspection Photos**  
**Location Name: Williams 24-21**  
**API Number: 125-09062**



**5. View of production tank.**



**6. View of production tank with insulation visible and metal covering peeling off tank.**

**Inspection Photos**  
**Location Name: Williams 24-21**  
**API Number: 125-09062**



**7. Production tank entry hatch removed. Note hydrocarbons on ground outside of entry. No caution or warning signs in place.**



**8. View of oily gravel and soil mixture in upper right of frame and flowline risers in center of frame.**

**Inspection Photos**  
**Location Name: Williams 24-21**  
**API Number: 125-09062**



**9. Additional view of flowline risers and fluid release around piping and under liner.**



**10. One of two flowline risers leaking from valve body and flowline to valve connection.**

**Inspection Photos**  
**Location Name: Williams 24-21**  
**API Number: 125-09062**



**11. Two of two flowline risers leaking from valve body and flowline to valve connection.**



**12. Additional view of impacted area with saturated soil under liner.**