

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/30/2025

Submitted Date:

01/05/2026

Document Number:

719500774

FIELD INSPECTION FORM

Loc ID 432260 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1700 LINCOLN ST STE 3950
City: DENVER State: CO Zip: 80203

Findings:

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, LARAMIE		cogccnotifications@laramie-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432258	WELL	PR	06/30/2021	GW	045-21934	Homer Deep Unit 9-41BH	PR
432261	WELL	PR	03/01/2018	GW	045-21935	Homer Deep Unit 9-41AH	PR
438407	WELL	PR	03/03/2015	GW	045-22488	Homer Deep Unit 9-41CH	PR

General Comment:

This is a field audit of the location, scout card, and related documents.

On 12/30/2025 at approximately 14:35, Compliance Inspector Matthew Morris conducted an on-site audit at LARAMIE ENERGY LLC, Homer Deep Unit/9-41 at Location ID #432260 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:		
Type	OTHER	
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.	
Corrective Action:		Date:
Type	CONTAINERS	
Comment:		
Corrective Action:		Date:
Type	BATTERY	
Comment:		
Corrective Action:		Date:
Type	TANK LABELS/PLACARDS	
Comment:		
Corrective Action:		Date:
Type	WELLHEAD	
Comment:	Wellhead signs are weathered and illegible.	
Corrective Action:	Comply with CECMC Signs and Markers Rules.	Date: 02/06/2026

Emergency Contact Number:		
Comment:	911/1-800-891-6191	
Corrective Action:		Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No _____
 Comment: _____
 Multiple Spills and Releases?

Fencing/:		
Type	OTHER	
Comment:	Bollards installed at Summit gas meter and on south end of separators.	
Corrective Action:		Date:
Type	WELLHEAD	
Comment:	Livestock fencing	
Corrective Action:		Date:

Equipment:		corrective date
Type: Bird Protectors	# 5	
Comment:		
Corrective Action:		Date:

Type: Gas Meter Run	# 1		
Comment:	Summit Midstream		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 3		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:

Date:

Inspected Facilities

Facility ID: 432258 Type: WELL API Number: 045-21934 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 432261 Type: WELL API Number: 045-21935 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 438407 Type: WELL API Number: 045-22488 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
				Material Handling And Spill Prevention		
		Ditches				
		Compaction				
Compaction						
Berms						
Gravel						
		Culverts				
		Check Dams				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>During the audit, the following compliance issue(s) were observed:</p> <p>1) Wellhead signs are weathered and illegible</p> <p>A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p>	morris	01/05/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404495102	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7403006
719500775	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7401726